

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED
OMB No 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

BTA Oil Producers

3a. Address

104 S. Pecos, Midland, TX 79701

3b. Phone No (include area code)

(432) 682-3753

4. Location of Well (Footage, Sec., T, R, M or Survey Description)

660' FNL & 1650' FEL NW/NE
Sec. 34, T22S-R34E

5. Lease Serial No

NMNM19143

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No

Maxus B, 8026 JV-P, #3

9. API Well No.

30-025-30661

10. Field and Pool, or Exploratory Area

Antelope Ridge, Bone Spring, West

11. County or Parish, State

Lea Co., NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BTA Oil Producers P&A'd this well as follows:

3/23/07 MI & RI CU. ND WH. NU BOP.

Release packer and POH with tubing and packer for 9-5/8" 53.5# casing.

RU WL. Pick up 9-5/8" CIBP on 2-7/8" tbg. RIH to 7,100'. Spot 50sx cmt plug @ 7100 - 6916' tagged.

Circ hole with 400 bbls 9.5 ppg salt gel.

Spot P&A plugs as follows:

78 sx @ 5914 - 5668'

78 sx @ 5292 - 5020' (tagged)

78 sx @ 3512 - 3262' (tagged)

75 sx @ 1840 - 1582' (tagged)

35 sx @ 100' to surface

Cut off wellhead and install dry hole marker

RECEIVED

FEB 28 2008

HOBBS OCD

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Pam Inskeep

Title Regulatory Administrator

Date 04/02/2007

Signature

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by (Signature)

Name
(Printed/Typed)

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

ACCEPTED FOR RECORD

Title

FEB 24 2008
Date

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

KZ