Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-20519 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE 🔀 FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District_IV 6. State Oil & Gas Lease No. 1220 S St Francis Dr., Santa Fe, NM 87505 E - 0789-1SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A MONSANTO STATE DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator 9. OGRID Number POGO PRODUCING COMPANY 17891 3. Address of Operator 10. Pool name or Wildcat P.O. BOX 10340, MIDLAND, PADUCA DELAWARE 4. Well Location 1650 feet from the SOUTH line and 1650' feet from the_ line Township 25 S Range 32 E NMPM 11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL 3,420' Pit or Below-grade Tank Application or Closure Pit type STEEL Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water ____ Pit Liner Thickness: _ Below-Grade Tank: Volume_____bbls; Construction Material _ 12. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON A PERFORM REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1-18-08 Set 4 1/2" CICR 24,300'. 1-22-08 Sqz. 10 sx. cmt. below CICR @4,300'. Pressure test below CICR to 750 PSI - Held. 1-23-08 Perf 4 holes @4,100'. Set 4 1/2" CICR @3,800'. Sqz. 100 sx. cmt. Test below CICR to 750 PSI. Approved for plugging of well bore only. 1-24-08 Spot 25 sx. cmt. - 1,010'. Spot 30 sx. cmt. from 385' to surface. Liability under bond is retained pending receipt 1-25-08 Install Dryhole Marker. of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or/closed according to NMOCD guidelines _____, a general permit ____or an (attached) alternative OCD-approved plan _____ P & A SUPV. SIGNATURE. TITLE_ _DATE _ E-mail address: Type or print name RANDALL MINEAR Telephone No. (432) 530-0907 For State Use Only

APPROVED BY_

Conditions of Approval, if any: