OCD-HOBBS

Form 3160-5 (April 2004)	UNITED STATE DEPARTMENT OF THE	FORM APPROVED OM B No 1004-0137 Expires March 31, 2007				
	BUREAU OF LAND MAN	5 Lease Senal No				
	NOTICES AND RE		LC-068281-B 6 If Indian, Allottee or Tribe Name			
Do not use ti abandoned w	his form for proposals rell. Use Form 3160-3	to drill, out of a enter an	6 II Indian, Alloutee of Tribe Name			
SUBMIT IN TR	IPLICATE- Other inst	tructions on reverse side. MAR (1.3.2003	7 If Unit or CA/Agreement, Name and/or No			
l Type of Well	Gas Well Other					
2 Name of Operator Sahara Oper		HARREM	8 Well Name and No. ConocoE Federal #1			
3a. Address		9. API Well No 30-025-31528				
P.O. Box 4130, Midland TX 79		10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec.,		Mason (Delaware) North 11. County or Parish, State				
1,650' FNL & 660' FEL, UL 1	I, Section 30, T26S, R23E NM					
· · · · · · · · · · · · · · · · · · ·			Lea County, New Mexico			
12. CHECK A	PPROPRIATE BOX(ES) TO	O INDICATE NATURE OF NOTICE	E, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing	Deepen Productio	n (Start/Resume) Water Shut-Off on Well Integrity			
✓ Subsequent Report	Casing Repair	New Construction Recomple	Other			
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Temporar Plug Back Water Dis	nly Abandonsposal			
If the proposal is to deepen dir Attach the Bond under which following completion of the in	ectionally or recomplete horizonta the work will be performed or pro- ivolved operations If the operation and Abandonment Notices shall be	ally, give subsurface locations and measured vide the Bond No. on file with BLM/BIA In results in a multiple completion or recomp	te of any proposed work and approximate duration thereof and true vertical depths of all pertinent markers and zones Required subsequent reports shall be filed within 30 days letion in a new interval, a Form 3160-4 shall be filed once reclamation, have been completed, and the operator has			
SEE ATTACHED PLUG	GED WELLBORE DIAGRA	M				
		kstring to 4,300'. RU cementer and dis displacing plugging mud. POOH with	splace hole with plugging mud. Pumped 40 sx C h tubing. SDFN.			
and pumped 40 sx C cmt. psi. Squeezed 55 sx C cm	. WOC and tagged cmt at 1,1 at @ 300', circulating cmt to si	04'. Perforated casing at 300'. RIH w	psi. Contacted BLM. RIH with tubing to 1,462', v/packer to 286', established rate at 2 BPM @ 500 packer and circulated 35 sx C cmt 286' to surface.			
05/20/08 Cut off wellhead	d & anchors, install dry hole r	narker.				
			APPROVED			
14 I hereby certify that the fore Name (Printed/Typed)	egoing is true and correct		FEB 2 8 2008			
James F. Newm	an, P.F.	Title Engineer, Triple	e N Services, Inc. 432-687-1994 5) C			
Signature Au	AL.	Date	BURE 2008 OF LAND MANAGEMENT			
THIS SPACE FOR FEDERAL OR STATE OF FICE USERLSBAD FIELD OF THE						
Approved by Approval, if any, are	William OC	DISTRICT SUPERMISOR/GER	100240			

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

PLUGGED WELLBORE SKETCH Sahara Operating Company

	•	banara operating oom		
			Da	te February 8, 2008
RKB @				
DF @				
GL @		Subarea .		
		Lease & Well No	Conoco E Federal #1	
		Legal Description	1650 FNL 660 FEL S30, T26S, R3	2E
	Topped off w/ 5 sx C cmt @ surface	County		w Mexico
	Topped on W/ 5 sx C cmt @ surface		Lea Clair	T MOXICO
		Field	D. D.l.	٠
S 5		Date Spudded	Rig Release	0
# 1 S 1 S 1 S		API Number	30-025-31528	
2.		Status	Plugged 02/05/08 State	Lease LC-068281-B
	Perf/sqz'd 90 sx C cmt 300 - surface			
	Penrsq2 d 30 sx C citt 300 - 3driaco			
[4] [14]				
131 1 191				
F				TAIPLE N
				SERVICES INC
				MIDLAND TE
		ļ	PLUGS SET 02/04 - 02/05/0	8
		1		
K		1	1) 40 sx C cmt 4,300 - 3,914 Tag	
			Circulated 95 bbls plugging mu	ıd
			3) Perforated @ 1,410, unable to	est_rate @ 1,200#
			4) 40 sx C cmt 1,462 - 1,104' Ta	nned
111 111		1	5) Dod/ood 000 000 000 0000 0000	y of a co
			5) Perf/sqz'd 90 sx C cmt 300 - s	ипасе
			6) Topped off w/ 5 sx C cmt @ su	urface
1.4				
				į
	8-5/8' csg @ 1,165' cmt'd to surface			
FV 118				
43 SA	40 sx C cmt 1,462 - 1,104' Tagged			
	Perforated @ 1,410', unable to establish r	ate @ 1.200 psi		
H	Teriorated (g) 1,410; dilabilo to obtablici.	G 1,522 PT		
		•		
di				
(f) (d)				
1.1 [.]				
- 191 - 1 <u>81</u>				
KS VI				
। 'स				
3				
ž				

Circulated hole w/ 95 bbls plugging mud 40 sx C cmt 4,300 - 3,914 Tagged

5-1/2" csg @ 4,280', TOC unknown

PBTD @ TD @ 4300'