

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop Cabinet Secretary Mark E. Fesmire, P.E.
Director

Oil Conservation Division

Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Luvironment"

30-Apr-08

FINLEY RESOURCES INC

1308 LAKE STREET #200 FT WORTH TX 76102

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION STATE W E D No.001				I-27-20S-36E	30-025-04353-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
04/29/2008	Routine/Periodic	Buddy Hill	Yes	No	5/23/2008	iLWH0812041757
	Violations					
	Absent Well Identification Sig	gns (Rule 103)				
Comments	on Inspection: No Well S	ign (Rule 103). WELL	NEEDS SIGN.	SECOND NOTICE		
LEA 407 STATE No.006				D 0 010 05E	30-025-24826-00-00	
LEA 407 ST	TATE No.006			D-2-21S-35E	30-025-24826-00-	-00
LEA 407 ST Inspection Date	TATE No.006 Type Inspection	Inspector	Violation?	D-2-218-35E *Significant Non-Compliance?	Corrective Action Due By:	-00 Inspection No.
Inspection Date		Inspector Buddy Hill	Violation? Yes	*Significant	Corrective	Inspection No.
Inspection Date	Type Inspection	•		*Significant Non-Compliance?	Corrective Action Due By:	
Inspection	Type Inspection Routine/Periodic	Buddy Hill		*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.

L W WHITE A No.001

B-2-21S-35E

J-27-20S-36E

30-025-25380-00-00

Inspection

04/29/2008

Type Inspection Date

Inspector

Buddy Hill

Violation?

Yes

*Significant Non-Compliance? No

Corrective Action Due By:

Inspection No. iLWH0812042347 8/2/2008

Violations

Surface Damage/Restoration

Routine/Periodic

Comments on Inspection:

P/A NOT READY to release. TANK BATTERY, TBG., TRASH NEED TO BE REMOVED AND

CELLAR NEEDS LEVELED.

STATE W E D No.002

30-025-26878-00-00

Inspection

Date

04/29/2008

Type Inspection Routine/Periodic Inspector **Buddy Hill** Violation?

Yes

*Significant Non-Compliance? No

Corrective Inspection No. Action Due By: iLWH0812041141 8/2/2008

Violations

Surface Damage/Restoration

Comments on Inspection:

P/A -NOT READY to release. MARKER HAS WRONG UNIT LETTER, JUNK PIPE ON EAST AND WEST SIDES OF LOCATION, OLD SIGN AND N/W ANCHOR AND PIT PLASTIC FLAGS NEED TO BE REMOVED AND CELLAR AREA NEEDS LEVELED, FIRST NOTICE

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely, J. W. Buddy. Hid

COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD OIL CONSERVATION DIVISION 1625 N FRENCH DRIVE HOBBS NM 88240



014H15215335 \$0.410 SOURCE PRODUCE OF A PR

FINLEY RESOURCES INC. 1308 LAKE STREET #200 FT. WORTH, TX 76102-0000