Submit 3 Copies To Appropriate District State of New Mexico Office	Form C-103
District I 1625 N French Dr., Hobbs, NM 88240	May 27, 2004 WELL API NO.
District II	30-025-32769
1301 W Grand Ave, Artesia, NM 88210 MAY OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM87410	STATE FEE
District IV 1220 S St Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name WEST DOLLARDHIDE DRINKARD UT
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other	8 Well Number 112
2 Name of Operator	9. OGRID Number 4323
CHEVRON U.S.A. INC. 3. Address of Operator	10. Pool name or Wildcat
15 SMITH ROAD, MIDLAND, TEXAS 79705	DOLLARHIDE TUBB DRINKARD
4. Well Location	
Unit Letter L: 1475 feet from the SOUTH line and 790 feet from the WEST line	
Section 32 Township 24-S Range 38-E NMPM County LEA	
11 Elevation (Show whether DR, RKB, RT, GR, etc.,	
3144'	
Pit or Below-grade Tank Application [] or Closure []	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PAND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
OTHER ADD PERFS & ACIDIZE 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
03-06-08: MIRU. 03-07-08: POOH W/TBG TO PARTED RODS. 03-10-08. SET TAC. TIH W/TBG TESTING TO 6000 PSI.	
TAG TOF @ 6783. DRILL OUT CIBP @ 6840. C/O TO 7374. 03-11-08: TIGHT SPOT @ 6430. C/O 6783-CIBP DRILL OUT	
CIBP. FINISH DRILLING CIBP & C/O TO 7374. 03-12-08: PUSH CIBP TO 6939. 03-13-08. PU WS. STOP ABOVE TOP	
PERF. 3-14-08: TIH W/MILL TO CLEAN UP BAD CSG @ 6430. 3-17-08: ROTATE MILL THRU BAD CSG @ 6430-6446. TITE SPOT @ 6919. ROTATE TO 6942. FELL OUT. TAG UP ON CIBP @ 6939. PUSH CIBP TO 6944. TITE SPOT @ 6430-6446. 03-18-	
08. FELL OUT @ 6432. ROTATE ON CIBP @ 6944. C/O TO 7038. 03-19-08: COMP DO TO TD @ 7375. 03-20-08: PERF 6024-	
48, 6100-24, 6166-90 RAN GR PU SONIC HAMMER. 03-21-08. TIH W/TBG TO SET SONIC HAMMER @ 7324 WATER	
WASH OLD PERFS 7324-6321. ACID WASH PERFS 6321-7324 SPOT SCALE INHIB ACR PERFS. 03-24-08: PU PKR & RBP.	
TIH ON TBG. SET RBP @ 6261 REL PKR PUH & SET @ 5955. PUH W/PKR TO 5923. TIH W/TBG TO TOP OF RBP @ 6261 REL PKR 03-25-08: SET PKR @ 5955 ACID W/2500 GALS 15% HCL. 03-26-08: SWABBING REL PKR. REL RBP. 03-27-08.	
PU BHA TIH ON TBG 03-28-08: SET TAC CHANGE FROM TBG TO ROD TOOLS. 03-31-08. TIH W/NEW ROD STRING.	
04-02-08: LOAD TBG. SPACE PUMP HANG WELL ON. RIG DOWN. FINAL REPORT	
	•
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-	
grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan [].	
SIGNATURE SIGNAT	
Type or print name Denise Pinkerton E-mail address: <u>leakejd@chevron.com</u> For State Use Only	Telephone No 432-687-7375
PETROLEUM ENG	NEER MAY 7 5 2008
APPROVED BY. TITLE DATE Conditions of Approval (if any)	