

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

May 27, 2004

RECEIVED

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

WELL API NO. 30-025-05164
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Shell Maxwell
8. Well Number 1
9. OGRJD Number 236378
10. Pool name or Wildcat SWD Devonian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD ☒

2. Name of Operator
Saber Resources LLC

3. Address of Operator
400 W Illinois, Suite 950, Midland, Texas 79701

4. Well Location

Unit Letter J : 1980 feet from the South line and 1650 feet from the East line
Section 27 Township 14S Range 37E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3821' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER ☒: pull for tbq leak, RIH w/pkr & tbq to test csg

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3/4/08 MI & RUPU. Start out of the hole with 4-1/2" IPC Inj tbq. Tbg parted @ 1415'
3/5/08 - 3/29/08 Fished out tbq & 7" Arrow set pkr
3/31/08 - 4/1/08 RIH w/bit (6-1/8"), 4-3/4" DC, jars, 3) 4-3/4" DC's & tbq. Tag up @ 13,447'. Clean out OH to 13,750'. Acidize OH interval w/10,000 gals of 15% NeFe HCL. POH.
4/3/08 - 4/4/08 RIH w/7" AS-1X pkr, on/off tool & 4-1/2" IPC tbq. Set pkr @ 12,737'. Circ'd pkr fluid. Pressured test csg to 600# for 30 minutes w/Maxie Brown witnessing test. RDPU & NUWH. Start WI on vacuum.

SWD-969

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

R. DOUGLAS KEATHLEY, VICE-PRESIDENT OPERATIONS

SIGNATURE: Doug Keathley TITLE: VICE-PRESIDENT OPERATIONS DATE: 4/28/08

Type or print name: Douglas Keathley E-mail address: doug@saberresources.com Telephone No. 432-685-0169

For State Use Only

APPROVED BY: Chris Williams OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE: MAY 28 2008
Conditions of Approval (if any):

