May 23, 2008

COMPLIANCE OFFICER

New Mexico Oil Conservation Division 1625 N. French Drive Hobbs, New Mexico 88240

Attention: Maxey Brown, Inspector

In reply to: Letter of Violation dated 08-May-08 Inspection No. iMGB0812926168 State 32 No. 001 Inspection No. iMGB0812925960 Martin No. 001 Inspection No. iMGB0812925298 Davenport No. 001 30-025-24592-00-00 30-025-24882-00-00 30-025-24995-00-00

5/30/2008

Dear Mr. Maxey:

Corrective actions listed in the subject letter have been made, and locations of these plugged wells are ready for re-inspection.

Please note that two electrical power poles were left at the State 32 No. 1 wellsite at the request of the landowner, who agreed to assume responsibility for them.

Also note that four electrical power poles remain onsite at the Davenport No. 1 location, again at landowner's request. Landowner assumes responsibility for this equipment

Should further information be required, please contact me. I can be reached by telephone at (918) 621-6533 and by e-mail at CSSwan@manhattanpetroleum.com.

Sincerely,

2. 6. .

Connie Swan Regulatory Administrator





The share and the press to the solution of the

P. O Box 35888 Tulsa, OK 74153-0888

(918) 621-6533

FAX (918) 621-6535

3. 100 1013