-Submit 3 Copies To Appropriate District Office	Diuto of How Monito		Form C-103		
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240 District II			30-025-33	5080	
311 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Lease		
District III 1000 Rio Brazos Rd Aztec NM 87410	00 Rio Brazos Rd., Aztec, NM 87410 strict IV 20 S. St. Francis Dr., Santa Fe, NM		STATE FEE		
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Lease No.		
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			,		
1. Type of Well: Oil Well Gas Well Other P&A Location			Wilson, 20005 JV-P		
2. Name of Operator			8. Well No.		
BTA Oil Producers			1		
3. Address of Operator			9. Pool name or Wildcat Grama Ridge; Morrow, East (Gas) 77690		
104 S. Pecos, Midland, TX 79701			Grama Ridge; Mo	rrow, East (Gas) 7/690	
4. Well Location					
Unit Letter C : 990 feet from the north line and 1650 feet from the west line					
. Section 26 Township 21S Range 34E NMPM Lea County					
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3689'					
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				ALTERING CASING	
TEMPORARILY ABANDON					
PULL OR ALTER CASING	MULTIPLE COMPLETION	ABANDONMENT CASING TEST AND CEMENT JOB			
OTHER:		OTHER:			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.					
BTA reclaimed this location as follows:					
4-23-2008 JESCO Pipeline moved onto location. Pits were leveled to original contours and the cellar was backfilled.					
Per 4-09-2008 telephone conversation with Mr. Buddy Hill, no seeding of the reclaimed area was required.					
a december 1980 de la companya de l					
	MAY 1 g 2003				
/			HARR	SOCO	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE 16M M	New TITLE	Regulatory Adminis	trator	DATE_ 05/10/08	
Type or print name Pam Inskeep pinskeep@btaoil.com Telephone No. (432) 682-3753					
(This space for State use)					
APPROVED BY					