Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

_		
OCI).H(DEBS

FORM APPROVED OMB NO. 1004-0137 Expires March 31, 2007

5. Lease Serial No

LC-032233(A)

Do not use this	form for proposals to drill or to re-enter an Use Form 3160-3 (APD) for such proposals.	
abandoned well.	Use Form 3160-3 (APD) for such proposals.	29 1

6. If Indian, Allottee or Tribe Name

Do not use this form for abandoned well. Use For	proposals to drill or a m 3160-3 (APD) for s	uch proposals.	WEU	. II Indian, 7th	Acce of Thoc Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side MAY 2.2.7808			7 If Unit or CA/Agreement, Name and/or No			
Type of Well X Oil Well Gas Well Other Name of Operator Occidental Permian Limited Partner Address	<u>'</u>	Stephens, 20.09	99, GRWY 5	Well Name as North Hobb Unit API Well No. 30-025-074	os G/SA No. 441	
P.O. Box 4294, Houston, TX 77210-		(713) 366-51	58	10. Field and P	ool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey	Description)			HODDS; Gra	yburg-San Andres	
330' FSL x 330' FEL, Letter P, Sec	:. 30, T-18-S, R-38	BE /		11. County or Lea Co.	Parish, State	
12. CHECK APPROPRIATE	BOX(ES) TO INDIC	ATE NATURE OF	NOTICE, REPO	RT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
X Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (S		Water Shut-Off Well Integrity X Other Open Additional Pay and Acidize	
1) MI x RU. ND WH x NU BOP. PC 2) Run bit x scraper to PBTD (3) Run packer x plug and test packer at 4070'. If leak is discuss options with engine 4) Perforate 4078'-80', 4090'- 5) Run 5-1/2" PPI tool with 67 15% HCL (max rate 3 bpm, may 10 bbls 15% HCL (max rate 3	OOH with ESP product (@ 4265'). squeezed perfs at s detected, move preer. 92', 4096'-4106'. '' spacing. Set parax press 3000 psi.	4094'-4154' to sacker to 4125'. & 4111'-18', 2 scker at 4163' and	If holds, go JSPF, 180 deg d acidize 416	to next st ree spiral 8'-4224' w idize_407 8	ep; if not, phasing. ith 20 bbls	
6) Do scale squeeze and POOH w 7) RBIH with ESP equipment. 8) ND BOP x NU WH. Turn well c 9) RD x MO x clean location.	·			MAY	1 8 2008	
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)		Title			RVISOR-EPS	
Mark Stephens			latory Compli	ance Analy	/st	
Mark Stephen		Date 4/22				
	S SPACE FOR FEDER		FICE USE	15.		
Approved by		Title]-/	Dat	с	
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations to	those rights in the subject	ant or Office lease	12	-		