Form 3160-5 (April 2004)	DEPARTMEN	TED STATES NT OF THE INTERIOR LAND MANAGEMEN'		CD-HOBBS	FORM APPROVED OMB NO. 1004-0137 Expires March 31, 2007 5. Lease Serial No.		
	SUNDRY NOTICES Do not use this form for bandoned well. Use For		to re-enter an	1000 japan 1.	NM-62666	tee or Tribe Name	
SL	IBMIT IN TRIPLICATE -	Other instructions of			7. If Unit or CA/A NM 70948B	Agreement, Name and	d/or No
2. Name of Operator XTO Energy Inc 3a Address 200 LORAINE, S 4 Location of Well (Foo 1980 Feet from		<u>TX 79701</u> Description) 980 Feet from the				ENT 911	
12.	CHECK APPROPRIATE	BOX(ES) TO INDIC	CATE NATURE OF	NOTICE, REPO	ORT, OR OTHE	R DATA	
TYPE OF	SUBMISSION		۲۰	YPE OF ACTION			
X Subseq	of Intent uent Report bandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Reclamatio	e	Water Shut-Off Well Integrity Other	
13. Describe Proposed	or Completed Operation (clearl			· · · · · · · · · · · · · · · · · · ·		proximate duration t	 there

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

4/29/08 MIRU Basic Well Service. MI rack 140 jts of 2-7/8" N-80 WS. MI Basic Rev Unit. PU & RIH w/6-1/8" bit, 6 - 4-1/8" DC on 2-7/8" N-80 tbg. Tag @ 3650'. L&T TCA to 500 psig for 20" w/no loss.

4/30/08 SITP "0" - SICP "0" RU Basic pmp. L&T TCA to 500 psig for 30" w/no loss. RU Swivel. Tag CIBP @ 3650'. Brk circ. D0 cmt & CIBP fr 3650' - 3660'. Push CIBP to 3952'. Lost circ. RD swivel & POOH w/2-7/8" N-80 tbg. LD BHA. Dump 450# 20/40 mesh sand down 7" csg for plug back. RU JW WL. PU & RIH w/CCL, 3-1/2" bailer w/2 sks of class "C" cmt. Tag PBTD @ 3930'. Unable to dump cmt. RD WL.

5-1-08 SICP "0". RU Dialog WL. PU & RIH w/3-1/2" cmt bailer & tag PBTD @ 3930'. Dump 4 sks of class "C" cmt. RD WL.

	· · · · · · · · · · · · · · · · · · ·		DTED EAD DE	
 I hereby certify that the foregoing is true and correct Name (Printed/Typed) 	Title	AUUE	PIED FUR RE	CUKD
Velma Gallardo	Regu	latory [
Vehne Hallardo	Date 05/13/	/08	<u> </u>	
THIS SPACE FO	R FEDERAL OR STATE C	OFFICE USE	J. Anos	
Approved by	Title		Date EAU OF LAND MANAGE	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			ARLSBAD FIELD OFFIC	
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212 makes	it a crime for any person knowing	ly and willfully to mak	e to any department or ager	new of the United

Continued on attached pages.

Title 18 U.S.C Section 1001, and Title 43 U.S.C Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

5/2/08

SICP "0". PU & RIH w/Sonic Hammer Tool on 2-7/8" WS. Tag PBTD @ 3,909'. PUH to 3,745'. Wash GB OH fr 3,745' - 3,900' w/216 BBW @ 5.0 BPM, 2,000 psig. Acidize GB OH fr 3,900' - 3,745' w/2,500 gals of 20% 90/10 acid. Flushed w/30 BFW. RD CUDD equipment. BLWTR 266. Ave rate 5.0, Ave press 1900 psig. Wait 1 hr. RU swab. BFL 1,350'FS. Made 8 runs in 2 hrs & rec 43 bbls of wtr & 0 oil. EFL 1,850' FS. BLWTR 223. RD swab. SWI & SDON.

DWC: \$13,200 **CWC:** \$43,200 **DMC:** \$0 **CMC:** \$0

Stimulation Zone:	Graybur	g.						
Event Desc:	Sonic Hammer Acid Job		Top Int	erval: 3,	745 Bottom 3,900 Interval:			
Event	Stage	Vol	Rate	Press				
Seq	Desc	<u>(gal)</u>	<u>(bpm)</u>	(psig)	Comments			
1	Wash	9,072	5.0	2,000.0	Wash GB OH fr 3,745` - 3,900` w/9# BW.			
3	Acid	1,008	4.7	2,100.0	Acidize GB OH fr 3,900` - 3,835` w/20% 90/10 acid.			
5	Acid	1,008	5.3	2,300.0	Acidize GB OH fr 3,835` - 3,770` w/20% 90/10 acid.			
7	Acid	500	5.3	2,000.0	Acidize GB OH fr 3,770` - 3,745` w/20% 90/10 acid.			
9	Flush	1,260	5.3	1,900.0	Flushed acid to btm perf w/9# BW.			
	Ttl Gals: 12,848							

5/3/08

SICP "0". PU & RIH w/Sonic Hammer Tool on 2-7/8" WS. Tag PBTD @ 3,909'. PUH to 3,745'. Wash GB OH fr 3,745' - 3,900' w/216 BBW @ 5.0 BPM, 2,000 psig. Acidize GB OH fr 3,900' - 3,745' w/2,500 gals of 20% 90/10 acid. Flushed w/30 BFW. RD CUDD equipment. BLWTR 266. Ave rate 5.0, Ave press 1900 psig. Wait 1 hr. RU swab. BFL 1,350'FS. Made 8 runs in 2 hrs & rec 43 bbls of wtr & 0 oil. EFL 1,850' FS. BLWTR 223. RD swab. SWI & SDON.

DWC: \$13,200 **CWC:** \$43,200 **DMC:** \$0 **CMC:** \$0

Stimulation Zone:	Grayburg				9. (1) 1978 (Table 1) 3. B. (2) 79. (3) 21 7. (2) 1971 (2		
Event Desc:	Sonic Hammer Acid Job		Top Int	erval: 3,	745 Bottom 3,900 Interval :		
Event	Stage	Vol	Rate	Press			
Seq	Desc	<u>(gal)</u>	<u>(bpm)</u>	<u>(psig)</u>	Comments		
1	Wash	9,072	5.0	2,000.0	Wash GB OH fr 3,745` - 3,900` w/9# BW.		
3	Acid	1,008	4.7	2,100.0	Acidize GB OH fr 3,900` - 3,835` w/20% 90/10 acid.		
5	Acid	1,008	5.3	2,300.0	Acidize GB OH fr 3,835` - 3,770` w/20% 90/10 acid.		
7	Acid	500	5.3	2,000.0	Acidize GB OH fr 3,770` - 3,745` w/20% 90/10 acid.		
9	Flush	1,260	5.3	1,900.0	Flushed acid to btm perf w/9# BW.		
Ttl Gals: 12,848							

5/6/08

SITP "0" - SICP"0". POOH LD 2-7/8" N-80 tbg & sonic hammer tool. PU & RIH w/2-7/8" slotted MA, 2-7/8" SN on 2-7/8" 6.5#, J-55, EUE, 8rd tbg. ND BOP. Set 7" TAC w/16 pts tens. NU WH. SWI & SDON. Note: New tbg in DWC.

DWC: \$25,000 **CWC:** \$72,200 **DMC:** \$0 **CMC:** \$0

Tubing Location: Lower

0	Parts with the part of the second	a han 196 parts ann an 1989 a' gan a' gan an 1989 an 1984 an 1 An 1986 an 1987	-R-20120 < 4K		
ZONE 1	Desc: Grayburg	Top Perf: 3,745.00	Btm Perf:	3,904.00	OH: Yes
Object 1	Desc: 7 22# w/OH fr 3745 - 3904	Id: PBTD	Depth:	3,904.00	
Object 2	Desc: 2-7/8	Id: SN	Depth:	3,857.00	
Object 3	Desc: 7	Id: TAC	Depth:	3,665.00	
			Тор	Btm	
<u>Qty</u> <u>Ty</u>	pe Description	<u>Cond</u>	<u>Depth</u>	<u>Depth</u>	<u>Length</u>
1 mar	nual 2-7/8 Slotted MA	New 3,8	58.94 3,	,873.94	15.00'
1 Oth	ner 2-7/8" API SN	New 3,8	57.84 3,	,858.94	1.10'

1	Tubing	2-7/8", 6.5#, J-55, EUE, 8rd, IPC Tubing (TK-70)	New	3,826.19	3,857.84	31.65'
5	Tubing	2-7/8", 6.5#, J-55, EUE, 8rd Tubing	New	3,668.00	3,826.19	158.19'
1		2-7/8" x 7" TAC	New	3,665.30	3,668.00	2.70'
121	Tubing	2-7/8", 6.5#, J-55, EUE, 8rd Tubing	New	0.00	3,665.30	3,665.30'
					Total	3,873.94'

Landed @ 3,873.94'

5/7/08

SITP "0" - SICP"0". PU & RIH w/pmp & rods as followed. 1-1/2" x 8' GA, 2.5 - 2" - RXBC - 24' - 3' pmp (Wilson pmp# EU-078), 1 - 1-1/2" K-Bar (New), 1" x 4' stabilizer sub (New), 11 - 1-1/2" K-Bars (New), 84 - 7/8" D-78 rods (New), 56 - 1" D-78 rods (New), 2 - 1" D-78 subs (4',4') & 1-1/2 x 26' SM PR. SWO HWO. RU pmp trk. Load tbg w/7 bbls of 2% KCL wtr. Press test to 500 psig. RD pmp trk. RDMO PU. SWI. Note: New rods in DWC. $\beta \omega T \beta$