

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr. Hobbs NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

RECEIVED
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
MAY 29 2008
HOBBS OCD

WELL API NO. 30-025-06925
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name JOYCE PRUITT
8. Well Number 2
9. OGRID Number 13046
10. Pool name or Wildcat EUMONT/YATES/7R/QUEEN
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
LANEXCO, INC.

3. Address of Operator
1105 WEST KANSAS, JAL, NM 88252

4. Well Location
Unit Letter 0 : 660 feet from the SOUTH line and 1980 feet from the EAST line
Section 31 Township 21S Range 37E NMPM County LEA

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;
feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Form C-103, www.enr.state.nm.us/oed.

13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions, Attach wellbore diagram of proposed completion or recompletion.

5-12-08-MIRU. 5-13-08-NDWH. NUBOP. POH with 107 jts 2 3/8" tbg. RIH and tag plug. 5-15-08-Circ. plugging mud and spot 25 sxs at 3338'. PUH to 2560'. Spot 25 sxs. PUH to 1300'. Spot 25 sxs. POH. WOC. RIH and tag @ 504'. PUH to 317'. Circ. 35 sxs to surface. POH. 5-16-08-RD. Cut off well head. Cut off anchors. Install dryhole marker. Level location. SD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Charles Mann TITLE PRODUCTION SUPT. DATE 5/28/08

Type or print name CHARLES MANN E-mail address: Telephone No. 505-395-3056

(This space for State use)

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER
Conditions of approval, if any:

JUN 20 2008
DATE