

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: September 30, 1990

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
LANEXCO, INC.

3. Address and Telephone No.  
1105 WEST KANSAS, JAL, NM 88252 505-395-3056

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UL: F, 2310' FNL, 1650' FWL  
Sec. 33, T25S, R37E

5. Lease Designation and Serial No.

LC-054667

6. If Indian, Allottee or Tribe Name

7. If Unit or C.A. Agreement Designation

8. Well Name and No.

EL PASO TOM FED #3

9. API Well No.

30-025-26918

10. Field and Pool, or Exploratory Area

LANGLIE MATTIX

11. County or Parish, State

LEA, NM

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or  
Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

05-06-08: MIRU. ND well head. NU BOP. Start in hole with MMCPI workstring. SDFD.

05-07-08: Run in hole and tag @ 2456'. Spot 25 sxs at 2465'. Circulate plugging mud. Pull up hole. Spot 25 sxs at 1195'. Pull out of hole. WOC. SDFD.

05-08-08: Run in hole and tag @ 966'. Run in hole to 519'. Circulate 50 sxs to surface. Rig down. Cut off well head. Cut off achors. Install dryhole marker. Level location. Clean up location.

**RECEIVED**

JUN 11 2008

**HOBBS OGD**

**ACCEPTED FOR RECORD**

JUN 7 2008

*T. Ames*

BUREAU OF LAND MANAGEMENT  
CARLSBAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct

Signed *Chad L. Mann*

Title **PRODUCTION SUPT.**

Date **05-22-08**

(This space for Federal or State office use)

Approved by  
Conditions of approval, if any:

Title

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side