Submit 3 Copies To Appropriate State of New Mexico Form C-103 District Office May 27, 2004 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N French Dr , Hobbs, NM 88240 MATON DIVISION District II 30-025-11751 1301 W. Grand Ave , Artesia, NM 5. Indicate Type of Lease South St. Francis Dr. 88210 STATE FEE District III Santa Fe, NM 87505 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S St Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS 7. Lease Name or Unit Agreement (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH SOUTH JUSTIS UNIT E PROPOSALS.) Gas Well Other 1. Type of Well: Oil Well 201 8. Well Number LEGACY RESERVES OPERATING LP 2. Name of Operator 9. OGRID Number 240974 3. Address of Operator P.O. BOX 10848 Pool name or Wildcat JUSTIS-BLINEBRY-TUBB-DRINKARÓ MIDLAND, TX 79702 4. Well Location __:__1980___feet_from the ___NORTH____ line and ____990___feet from the __West_ line. Unit Letter Ε R37E **NMPM** Township T25S Range County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3087' KB Pit or Below-grade Tank Application
or Closure Distance from nearest fresh water well_____ Distance from nearest surface _Depth to Groundwater__ water_ bbls; Construction Material Pit Liner Thickness: mil Below-Grade Tank: Volume _ 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON □ REMEDIAL WORK ALTERING CASING □ PERFORM REMEDIAL WORK **CHANGE PLANS** COMMENCE DRILLING OPNS. P AND A TEMPORARILY ABANDON \Box \Box CASING/CEMENT JOB **PULL OR ALTER CASING** MULTIPLE COMPL П CANCEL FRAC JOB DUE TO BAD CASING: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. START DATE: 5/1/08 MIRU. RIH w/ 6 1/8"bit and scraper and tag at 5985'. Work tbg down to 5040'. RIH w / 6 1/8" bit, 6-4 1/2" drill collars and tagged at 4999' Rig up reverse unit and drilled out to 5900' to 5969'. RIH w/ bailer. Tag fill at 5978' and clean out to 5985'. Run GR/CNL/CCL log from 5981' to 4000' Perforate 5000'-5014-5253-5339-5648-5725-5743-5820-5831-5842-5872', total 11 holes. Spot 2000 gal 15% NEFE HCL acid across B-T-D perfs 5000' to 5920' in preparation of acid and frac job. RIH w/ 7" packer and 3 1/2" frac string. Set packer at 4924. Attempt to load backside. Did not load and on vacuum. Move pkr and reset multiple times. Could not load annulus and well on vacuum. Suspect csg leaks. Rig up Weatherford Wireline and run 40-arm casing inspection log from 5025' to 3200'. Inspection log showed potential holes at 4015'-4599'-4717-4729-4731'-4741-4748-4832-4908-4921-4944-4946' and missing casing from 4975' to 5025' (btm logged depth). RIH w/ 7" packer and RBP. Set pkr and RBP at multiple depths to test casing. Confirmed multiple casing leaks with pump-in tests. Legacy ordered cancellation of frac and further work pending evaluation and partner approval of casing repair. RIH w/ prod equip. Put well back on pumping production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines _, a general permit _ or an (attached) alternative OCD-approved plan . MULCENT TITLE: SENIOR ENGINEER DATE 7/2/2008 SIGNATURE Type or print name **KENT WILLIAMS** E-mail address: Telephone No. (432)689-5200 For State Use Only JUL 0 7 2008 **APPROVED** OC DETRICT SUPERVISOR/GENERAL MANAGER DATE Conditions of Approval (if any):