

District I

1625 N. French Dr. Hobbs NM 88240

District II

1301 W. Grand Ave. Artesia, NM 88210

District III

1000 Rio Brazos Rd. Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-025-26347

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-2330

7. Lease Name or Unit Agreement Name

STATE AC

8. Well Number

2

9. OGRID Number

13046

10. Pool name or Wildcat

EUMONT/YATES/7R/QUEEN

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

LANEXCO, INC.

3. Address of Operator

1105 WEST KANSAS, JAL, NM 88252

4. Well Location

Unit Letter E : 1980 feet from the NORTH line and 660' feet from the WEST lineSection 5Township 19S Range 37E

NMPM

County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ; feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
<http://www.state.nm.us/oed/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 5/27/08: MIRU. ND Wellhead. NU BOP. RIH with workstring. Tag @ 2590'.

Circ. plugging mud. Spot 25 sxs @ 2590'. PUH to 1500'. Spot 25 sxs. PUH to 550'. Circ. 40 sxs to surface. 5/28/08: ND BOP. RDP. Cut off wellhead. Cut off anchors. Install dryhole marker. Level location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.SIGNATURE Charles Mann TITLE PRODUCTION SUPT. DATE 7/9/08Type or print name CHARLES MANN E-mail address: Telephone No. 505-395-3056

(This space for State use)

APPROVED BY Chris Williams TITLE OC DISTRICT SUPERVISOR/GENERAL MANAGER DATE JUL 15 2008

Conditions of approval, if any: