

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

WELL API NO. <u>30 005 21174</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <u>Williams</u>
8. Well Number <u>1</u>
9. OGRID Number
10. Pool name or Wildcat <u>Wildcat</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
CW Trainer

3. Address of Operator
P.O. Box 754 Midland TX 79702

4. Well Location

Unit Letter C : 400 feet from the North line and 2300 feet from the West line

Section 33 Township 14S Range 31E NMPM County Chaves

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐


COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. 100' plug @ 3400'-3300'
2. Circulate hole w 9.5# mud
3. Cut off & pull 4 1/2" CSG @ ±3100'
4. 100' plug @ 3150'-2940' & tag
5. 100' plug @ 2300'-2200' & tag
6. 100' plug @ 229'-129' & tag
7. 10 SX @ surf.
8. Set dry hole marker



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John Gould Jr. TITLE Engr DATE Oct 30, 03

Type or print name John Gould Jr. Telephone No. 432 687 4338

(This space for State use)

APPROVED BY Gary W. Wink TITLE FIELD REPRESENTATIVE DATE OCT 30 2003

Conditions of approval, if any:

PLUGGING & ABANDONMENT WORKSHEET (4 STRING CSNG)

OPERATOR C. W. Trainer
LEASENAME Williams

LEASENAME Williams

SECT	33	TWN	WELL #	1
			145	RNG 31E

SECT 33 TWN 145 RNG 31E
FROM 440 N/S L 2300 L/W L

FROM 440 N/S L 2300 E/W L

TD: 4726 FORMATION @ TD San Andre

PBTD: 4661 FORMATION @ PBTD San Ana

9 5/8
@ 17.9
TOC SURF

@ 179
TOC surf

TOC surf

7"
@ 2990
TOC Surf

@ 2990
TOC Surf

TOC Surf

TOC

TOC

3379
3391

3391

4330

4350

4370

4390

4 1/2
@ 4685
TOC 3110

@ 4685
TOC 3110

TOC 3110

TD 4.726

	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	9 3/8"	179'	surf	visual	
INTMED 1	7"	2990	surf	visual	
INTMED 2	4 1/2"				
PROD	4 1/2"	4685	3110	Temp Sur.	
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1			PERFS	-	
INTMED 2			OPENHOLE	-	
PROD					

• **REQUIRED PLUGS DISTRICT 1**

RUSTLER (ARMYD)	
YATES	
QUEEN	
GRAYBURN	
SAN ANDREW	
CAPTAIN REEF	
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BRIMLEY CANYON	
HONG SPINDO	
CLORRETA	
WILDERKY	
TURB	
DEBICARD	
ASO	
WIC	
FENN	
STELAWN	
ATDEA	
MOORLOW	
MOSE	
OSVORIAN	

PLUG	TYPE PLUG	BACKS CMNT	DEPTH
EXAMPLES			
PLUG #1	OH	25 SXS	9850'
PLUG #2	SHOE	50 SXS	8700'-8800
PLUG #3	CIBP/33'		5300
PLUG #3	CIBP	25 SXS	3300
PLUG #4	STUB	50 SXS	4600'-4700'
PLUG #7	RETNR SQZ	200 SXS	400
PLUG #8	SURF	10 SXS	0-10'
PLUG #1			
PLUG #2			
PLUG #3			
PLUG #4			
PLUG #5			
PLUG #6			
PLUG #7			
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #			
PLUG #			
PLUG #			
PLUG #			