Form 3160-5 (February 2005)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIPCONS. Division BUREAU OF LAND MANAGEMENT 1625 N. French Dr.

OMB No. 1004-0137 Expires: March 31, 2007

FORM APPROVED

SUNDRY NOTICES AND REPORTS ON WELLS And not use this form for proposals to drill of to resenter an

5. Lease Serial No. NM 021097A 6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.						
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well Gas Well Other					8. Well Name and No. Federal H No.2	
2. Name of Operator H. L. Brown operating, L.L.C.					9. API Well No. 30-041-20934	
			(include area code) i-5216		10. Field and Pool or Exploratory Area Bluitt Wolfcamp	
4. Location of Well (Footage, Sec., T.) 660 FN & EL of Sec 5 T-8-S, R-37-E			11. Country or Parish, State Roosevelt County, NM			
12. CHEC	K THE APPROPRIATE BO	OX(ES) TO INDI	CATE NATURE	OF NOTIC	E, REPORT OR OTHE	ER DATA
TYPE OF SUBMISSION TYPE OF ACT						
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair	New (are Treat Construction	Reco	action (Start/Resume) mation mplete	Water Shut-Off Well Integrity Other
Change Plans Final Abandonment Notice Convert to Injection		Plug I	and Abandon Back		pporarily Abandon ter Disposal	
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 7-28-08: RU swab to find IFL @ 7000' - recvered 4 BLW w/ small show. Loaded tbg, released pkr and POH. 7-29-08: Perfed Wolfcamp 8484-94' (2spf -20 holes) w/ 3-1/8" csg gun. TIH w/ pkr to set @ 8372'. Swb'd well dry. 7-30-08: Acidized w/ 2000gals 15% NEFE; zone went on vacuum. Swb'd well dry - 98 BLWTR. 7-31-08: RU swab to find IFL @ 5100', swab'd well dry - weak blow after swab. 8-01-08: RU swab to find IFL @ 7300', swab'd well dry - weak blow after swab. RD PU. Well shut in while evaluating further prospects AUG 1 1 2008 AUG 1 1 2008						
I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Carlton Wheeler			Title Operations Manager			
Signature CarHon Wheeler			Date 08/04/2008			
ACCEPTED F	OR REUS RPACE	FOR FEDE	RAL OR STA	ATE OF	FICE USE	
Conditions of approval, if any Austrache that the applicant holds legal or equitable entitle the applicant to conduct operations Title 18 U.S.C. Section 1001 apprinted 5	d.7 Ap. 2008 of this notice do title to those rights in the subjutces.	es not warrant or e	Title certify ould Office		I	Date I or agency of the United States any false.
fictitious or fraudulent statements du reput	definition and an investor w	ithin its jurisdiction	n.	~ #11HBHY I	o make wany separtiten	a or about of the orthogogenes mil tanks