

Submit 3 copies to Appropriate District
Office

DISTRICT I

1625 N. French Dr., Hobbs NM 88240

DISTRICT II

1301 W. Grand Avenue, Artesia NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec NM 87410

DISTRICT IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, New Mexico 87504-2088

Form C-103

Revised March 25, 1999

WELL API NO. 30-025-29335
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Shipp ZI
8. Well No. 3
9. Pool Name or Wildcat Lovington Penn NE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
105 South 4th Str., Artesia, NM 88210

4. Well Location
Unit Letter **E** **1470** feet from the **North** line and **660** feet from the **West** line
Section **27** Township **16S** Range **37E** NMPM County **Lea**

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3786.7' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Approved as to plugging of the Well by _____
Liability under bond is retained until surface restoration is completed

10-13-03 to 10-22-03 RIH w/50 joints 2-7/8" tubing. Ran free point; bottom @ 11362', stuck @ 11350', free @ 11315'. Cut @ 11315' and POOH w/tubing. Set CIBP @ 10890' and dumped 35' cement on top. Tagged cement @ 10850'. Circulated hole w/mud-laden fluid. POOH to 7948'. Spot 25 sx Class C Neat 7948-7701'. Perforated 5-1/2" casing @ 4922'. Set packer @ 4550' and squeezed w/35 sx Class C Neat. WOC. Tagged plug @ 4747'. POOH w/packer. Perforated @ 4369'. Set packer @ 4050' and squeezed w/35 sx Class C Neat. WOC. POOH w/packer. Perforated @ 2170' and set packer @ 1800'. Squeezed w/35 sx Class C Neat. WOC 4 hrs. and tagged plug @ 2019'. POOH w/packer. Perforated @ 487'. Circulated 139 sx Class C Neat down 5-1/2" casing and up to surface of 8-5/8" casing. WOC 4 hrs. Cement @ surface. Cut off wellhead and installed dry-hole marker.

WELL IS PLUGGED AND ABANDONED. FINAL REPORT.

I hereby certify that the information above is a true and complete to the best of my knowledge and belief.

SIGNATURE Stormi Davis TITLE Regulatory Compliance Technician DATE 10/30/03

Type or print name Stormi Davis Telephone No. 505-748-1471

(This space for State use)

APPROVED BY Ray W. Winters DATE NOV 10 2003
Conditions of approval, if any: FIELD REPRESENTATIVE II/STAFF MANAGER