Office State of New Mexico	Form C-103
Energy, Minerals and Natural Resources	Revised March 25, 1999
DISTRICT II	E 24254
DISTRICT III 1301 W. Grand Avenue, Artesia NM 88210 30-02 1220 South St. Francis Dr. 5. Indicate Type of L	5-34354 ease
1000 Rio Brazos Rd., Aztec NM 87410 Santa Fe, New Mexico 87504-2088 STATE X	FEE 🗌
DISTRICT IV 6. State Oil & Gas Le 1220 S. St. Francis Dr., Santa Fe, NM 87505	ease No. 0629
	nit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
	N State Com
Oil Well Gas Well X Other	
2. Name of Operator Yates Petroleum Corporation 8. Well No.	4
3. Address of Operator 9. Pool Name or Wile	1 deat
105.0 11 11 01 11 11 11 11 11 11 11 11 11 11	Atoka, North
4. Well Location	,
Unit Letter J: 1650 feet from the South line and 1980 feet from the	East line
Section 10 Township 16S Range 35E NMPM County	Lea
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3994' GR	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN	, <u> </u>
PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	
OTHER: OTHER: Return to Production	X
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.	
or recompilation.	
10-27-03 RU slickline unit, pull blanking plug @ 11811' and return well to production.	17 18 19 20 27 22 22 22 22 22 22 22 22 22 22 22 22
or recompilation.	17 18 19 20 27 22 25 26 26 26 26 26 26 26 26 26 26 26 26 26
or recompilation. 10-27-03 RU slickline unit, pull blanking plug @ 11811' and return well to production. Well is producing from Atoka 11892-11903'.	21-18 19 30 3722 324 25 25 25 25 25 25 25 25 25 25 25 25 25
10-27-03 RU slickline unit, pull blanking plug @ 11811' and return well to production. Well is producing from Atoka 11892-11903'.	
Thereby certify that the information above a true and complete to the best of my knowledge and belief. SIGNATURE Type or print name Stormi Davis T0-27-03 RU slickline unit, pull blanking plug @ 11811' and return well to production. ### Type or print name 11892-11903'. Talephone No.	SI-1EOE GO
Thereby certify that the information above a true and complete to the best of my knowledge and belief. SIGNATURE Stormi Davis To recompilation. 10-27-03 RU slickline unit, pull blanking plug @ 11811' and return well to production. Well is producing from Atoka 11892-11903'.	10/30/03