Form 3160-5 (August 2007)

1. Type of Well

3a. Address

X Oil Well

Name of Operator

Gas Well

Samson Resources Company

12.

Other

200 N. Loraine St., Ste 1010; Midland, TX 79701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1890' FSL & 660' FWL Sec. 11-20S-34E

TYPE OF SUBMISSION

Notice of Intent

Subsequent Report

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-HOBBS

3b. Phone No. (include area code)

(432) 683-7063

Deepen

Fracture Treat

Plug Back

New Construction

Plug and Abandon

FORM APPROVED

OMB NO	1004-0137
Expires Ju	ly 31, 2010

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

Acidize

Alter Casing

Casing Repair

Change Plans

Convert to Injection

5. Lease Serial No. NMNM0631 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. Federal 11-20-34 No. 3 9. API Well No. 30-025-30424 10. Field and Pool, or Exploratory Area Lea;Bone Springs 11. County or Parish, State NM CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Perf Recomplete Temporarily Abandon Third Bone Spring Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

5/2/2008 - 6/13/2008

- POH w/rods and pump. Rls Tac. NU BOP.
- Load hole. POH w/tubing.
- 3. GIH w/bit and scraper on 2 3/8".
- Clean out to 11000'. POH. RU WL.
- 5. Perf Third Bone Spring (10860'-10870', 10912'-10922') 2 spf.
- 6. GIH w/retrv pkr. Set pkr @ 10715'. ND BOP NU frac valves.
- Breakdown perfs. Acdz. Swab back load.
- 8. Frac. Flow back. RU slickline. Set blanking plug in o/o tool.
- 9. ND frac valves. NU BOP. Rls o/o tool. POH LD frac string.
- 10. GIH w/tubing. Latch o/o tool. ND BOP. NU tree.
- 11. RU slickline. Retrieve blanking plug.
- 12. Flow test.

ACCEPTED		RECORD		

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Kenny Krawietz	Title District Eng	BURFAÙ OF LAND MANAGEMENT Di neer CARLSBAD FIELD OFFICE
Signature Vaccy Viceres	Date 6/23/2008	2 ' wii.
THIS SPACE FOR	FEDERAL OR STATE OFFICE U	SE
Approved by Chus Welliams	Title	Date
Conditions of approval, if any, are attached Approval of this notice does not warrant of the applicant holds legal or equitable title to those rights in the subject lease which wou entitle the applicant to conduct operations thereon.	or certify that Office	

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.