

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1960, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-925-05202
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Denton North Wolfcamp Unit Tract 4
8. Well No. 1
9. Pool name or Wildcat Denton Wolfcamp


SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator Stephens & Johnson Operating Co.	
3. Address of Operator P.O. Box 2249, Wichita Falls, TX 76307-2249	
4. Well Location Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 35 NW NW Township 14S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3824 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-03-03 Spot 25 sx cmt. @ 9225'.
10-06-03 Tag plug @ 8964'.
10-06-03 Mix mud & circ. hole w/ mud.
10-06-03 Spot 25 sx cmt. @ 6300'.
10-07-03 Cut 5-1/2" csg. @ 4696'.
10-08-03 Spot 50 sx cmt. @ 4832'.
10-09-03 Tag plug @ 4613'.
10-09-03 Spot 35 sx cmt. @ 3150'.
10-09-03 Spot 35 sx cmt. @ 2200'.
10-09-03 Spot 125 sx cmt. from 412' to surface.
10-09-03 RDMO. Cut off wellhead, install dry hole marker, & clean location.

Approved as to plugging of the Well Bore
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information shown is true and complete to the best of my knowledge and belief.

SIGNATURE Randall Minear TITLE Agent DATE 10-15-03
TYPE OR PRINT NAME Randall Minear TELEPHONE NO. 432-530-0907

(This space for State Use)

APPROVED BY Larry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE NOV 13 2003
CONDITIONS OF APPROVAL, IF ANY: