

RECEIVED

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

HOBBS OCD

WELL API NO.

30-025-29203

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

JORDAN B

8. Well Number

2

9. OGRID Number

236790

10. Pool name or Wildcat

(79880) Laguna; Seven Rivers

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

XOG OPERATING, LLC

3. Address of Operator

P. O. BOX 352, MIDLAND, TX 79702

4. Well Location

Unit Letter G : 1980 feet from the North line and 2310 feet from the East lineSection 11 Township 20S Range 35E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness:

mil

Below-Grade Tank: Volume

bbls;

Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☒CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Liability under Bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.emnrd.state.nm.us/oed.

6/30/08 Notify OCD.

7/1/08 MIRU Mayo Mars. Pooh w/166 rods. Nd wellhead. NU BOP, RIH & spot 65 sacks cmt @ 4,186'. SDFD.

7/2/08 RIH & tag @ 4,032'. Circ plugging mud. Test csg. Spot 50 sacks @ 2,050'. PUH to 470' & spot 55 sacks. POH. WOC and SDFD

7/3/08 RIH & tag @ 358'. Puh to 60'. Circ 30 sacks to surface. SDFD.

7/7/08 Jack hammer cmt in cellar & clean out.

7/10/08 Cut well head off & install PA marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

Angie Crawford

TITLE Production Analyst

DATE 8/26/08

Type or print name

E-mail address:

Telephone No.

For State Use Only

acrawford@xogoperating.com

432-683-3171

APPROVED BY:

T. W. Hill

OCD FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

Conditions of Approval (if any):

SEP 03 2008