(Instructions on page 2)

UNITEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.

	,	LIABOR	7 Umgor A/Agreement, Name and/or No.
SUBMIT IN TRI	PLICATE - Other instructions or	Neverse 1000	7 Aut Officer (A/Agreement, Name and/of No.
1. Type of Well	Gas Well Other	white	8. Well Name and No
2. NameofOperator ConocoPhillips Company			MCA Unit #291 9 API Well No.
3a. Address 3b PhoneNo. (include area code) 3300 N. "A" Street, Bldg. 6 Midland TX 79705 (432)688-6884			30-025-23836 / 10 Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R, M., or Survey Description)			Maljamar, Grayburg-San Andres
1345' FSL 1295' FWL UL: L, Sec: 19, T: 17S, R: 32E			11. County or Parish, State Lea County New Mexico
12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Deepen AlterCasing FractureT Casing Repair New Cons Change Plans Plug and A Convert to Injection Plug Back	truction X Recomplete bandon Temporarily Al	Well Integrity Other
Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Reclaim location and access roads 1. Remove caliche pad and roads. 2. Remove all contaminated soil average 4-6' deep. Deliver to CRI landfill. 3. Replace with 3' caliche barrier, level and compact. 4. Put in 2' - 3' toposoil cap on entire location, level and shape to natural. 5. Build earthen berms on entrances to prohibit vehicular traffic. 6. Seed all disturbed areas with BLM # 2 seed mixture with approved seed. Met with BLM Agent, Trish Badbear, for procedures and guidlines before starting job. Joy Canada to pale to pale 5. Store CEPTED FOR PLAND MANAGEMENT and the procedure of the proc			
Badbear was present at the job completion for job and approval and to witness seeding.			
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)			
Celeste G. Dale		Title Regulatory Spe	cialist
Signature Mulate A. Val. Date 08/26/2008			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by		Title	Date
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon		lease Office	y to make to any department or agency of the United
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United			