

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter abandoned well. Use Form 3160-3 (APD) for such proposals.

RECEIVED
OCD-HOBBS
SEP 26 2008
HOBBS (17)

5. Lease Serial No.
LC-032233(A)
6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other WIW

2. Name of Operator

Occidental Permian Limited Partnership Attn: Mark Stephens, Rm. 20.099

3a. Address

P.O. Box 4294, Houston, TX 77210-4294

3b. Phone No. (include area code)

(713) 366-5158

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1400' FSL & 2430' FEL, Letter J, Sec. 30, T-18-S, R-38-E

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No.

North Hobbs G/SA No. 333 Unit

9. API Well No.

30-025-28955

10. Field and Pool, or Exploratory Area

Hobbs; Grayburg-San Andres

11. County or Parish, State

Lea Co. NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Acidize ☐ Deepen ☐ Production (Start/Resume) ☐ Water Shut-Off
☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity
☐ Casing Repair ☐ New Construction ☐ Recomplete ☒ Other OAP and
☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon acid stimulate
☐ Convert to Injection ☐ Plug Back ☐ Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

- 1) MI x RU. NU BOP. POOH with injection equipment.
- 2) Run bit x scraper to 4328' (PBSD).
- 3) Run GR/CCL correlation log from PBSD to 3300'.
- 4) Perforate at 4196' - 4204', 4210' - 4220', & 4225' - 4234', 2 JSPF, 180 deg. spiral phasing.
- 5) Set treating packer at 4100' and acidize perfs with 2200 gal. 15% HCL (max. rate 3 bpm, max. press. 3000 psi).
- 6) Run bit to bottom to look for salt bridges.
- 7) Pump scale squeeze x RBIH with injection equipment.
- 8) ND BOP x NU WH. Pressure test casing x chart for the NMOCD.
- 9) RD x MO x clean location. Turn well over to injection.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Mark Stephens

Title

Regulatory Compliance Analyst

Date

9/4/08

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/S/ DAVID R. GLASS

Title

PETROLEUM ENGINEER

Date

SEP 20 2008

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.