

Office

District I

1625 N French Dr, Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr, Santa Fe, NM 87505

Energy, Minerals and Natural Resources

## OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

May 27, 2004

WELL API NO.

30-025-09868

5. Indicate Type of Lease

STATE ☐ FEE ☒ BLM ☐

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement Name

B.C. Dickinson A1

8. Well Number # 2

9. OGRID Number

228051

10. Pool name or Wildcat

Denton (Devonian)

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☒ ~~Injection Well~~

2. Name of Operator

Americo Energy Resources, LLC

3. Address of Operator

7575 San Felipe, Suite 200, Houston, TX 77063

4. Well Location

Unit Letter L : 2240 feet from the South line and 400 feet from the West lineSection 1 Township 15S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3808' GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☒ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☐CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

In 2006, top of the fish was tagged @ 7055'. the est.'d top of cmt behind the 7" csg is at 8100'.  
 MIRUWOR, RIH W/ 2 7/8" tbing to 7,005' spot 25' of cmt, poh w/ tbing  
 R/U wire line trk, rih & tag top of cmt, poh. R/d wire line trk, rih w/ 2 7/8" tbing circ hole w/ 2%  
 kcl water. Pressure test to 500 psi for 30 min's if good, POH w/ tbing laying down. RDWOR. Set  
 up H-15.

Condition of Approval: Notify OCD Hobbs  
 office 24 hours prior to running MIT Test & Chart.

**DENIED**

Remedial Work to begin by 11-6-08  
 [Signature]

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Ehsan Bayat TITLE Regulatory Analyst DATE 9-26-08.  
 Type or print name: Ehsan Bayat E-mail address: ehsan.bayat@americoenergy.com Telephone No. 713-984-9700

For State Use Only

APPROVED BY: \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Conditions of Approval (if any): \_\_\_\_\_



# New Mexico Energy, Minerals and Natural Resources Department

**Bill Richardson**  
Governor

**Joanna Prukop**  
Cabinet Secretary  
**Reese Fullerton**  
Deputy Cabinet Secretary

**Mark Fesmire**  
Division Director  
Oil Conservation Division



October 6, 2008

Mr. Oscar Nosrati;

This letter is to notify you that the attached C-103 requesting T/A status for the B.C. Dickinson A1 #2 well API # 30-025-09868 has been denied.

This well was required to have had remedial work performed on or prior to 1-23-2007 by District 1 supervisor Chris Williams. No work has been reported since that time.

This well has a cement top 1100' below top of fish. The top of fish is 5000' above the production zone. We have no way of knowing casing integrity below 7000'.

Therefore, you are hereby ordered to begin work to repair or plug this well no later than November 6, 2008.

Failure to comply will result in this matter being sent to legal staff.

If you need further help, please feel free to contact me at 575-393-6161 ext. 114.

Sincerely;

L.W. "Buddy" Hill

