

Submit 3 Copies to Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-08094
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> FED <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Young Unit
8. Well Number 19
9. OGRID Number 19086
10. Pool name or Wildcat Penrose

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Injection

2. Name of Operator  
State of NM, Formerly Sierra Blanca Oper.

3. Address of Operator  
1625 N. French Dr., Hobbs, NM 88240

4. Well Location  
Unit Letter H : 2310 feet from the North line and 990 feet from the East line  
Section 20 Township 18s Range 32e NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU Plugging equipment, pull injection equipment if any in hole.
2. Set CIBP @ 3775' Circ. Hole w/ MLF, Spot 25 sx. Cmt. on top of CIBP.
3. Spot 25 sx. Cmt. @ 2430', BOS
4. Perforate csg. @ 1085' and squeeze with 40 sx. Cmt., WOC and tag.
5. Perf. @ 350' and circulate cmt. to surface inside and out.
6. Cut off well head, install dry hole marker and clean location.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Carly W. Hill*

TITLE

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

OCT 15 2008

Type or print name

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

*Carly W. Hill*

TITLE

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

OCT 15 2008

Conditions of Approval (if any):

**(2 STRING CSNG)**

30-025-08094

WELL # 19

185 RNG 328

990 EWL

FORMATION @ TD \_\_\_\_\_

FORMATION @ PBTD

19086

Engl.

$\frac{85}{8}"$   
 @  $\frac{1035'}{8}$   
 TOC ?

Top Perf.  
3816

$5\frac{1}{2}''$   
 @  $4135'$   
 TOC ?

TD 4135'

	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	8 2/8"	1035'	P		
INTMED 1					
INTMED 2					
PROD	5 1/2"	4135	P		
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1			PERFS	-	
INTMED 2			OPENHOLE	-	
PROD					

**\*REQUIRED PLUGS DISTRICT I**

RUSTLER (ANGYD)	
YATES	
QUEEN	
GRAYBURG	
SAN ANDREW	
CAPTAIN REEF	
DELAWARE	
BELL CANYON	
CHEERY CANYON	
BRUSHY CANYON	
BONE SPRING	
OLOWIETA	
BLINEBRY	
TUBE	
DRINGCARD	
ALBO	
WC	
PENN	
STRAWN	
ATOKA	
MORROW	
ATTS	
ORVORGAN	

[illegible]