

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999


OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-20137
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Chevron USA Inc		6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd, Midland, TX, 79705		7. Lease Name or Unit Agreement Name: State BB
4. Well Location Unit Letter <u>D</u> : <u>440</u> feet from the <u>North</u> line and <u>990</u> feet from the <u>West</u> line Section <u>2</u> Township <u>25-S</u> Range <u>37-E</u> NMPM <u>Lea</u> County		8. Well No. 2
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Langlie Mattix 7 Rvrs Queen Grayburg

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. RU on B-String west-side, RIH Tag CIBP at 3700, spot 65sx, plug from 3700 to 1300 (Blinbry), Tag at 1318.
2. RU on A-String east-side, set 2 7/8 CIBP at 3450, spot 55sx, plug from 3450 to 1300 (Grayburg-San Andres), Tag at 1295.
3. Cut both strings at 1300, spot 160sx, plug from 1300 to 850 (Stub, T-Salt, 9 5/8 Shoe), Tag at 1171, Re-spot w/100sx, Tag at 708.
4. Displace hole with MLF 9.5# Brine w/12.5# gel P/BBL.
5. Spot 90sx, plug from 257 to Surf, Tag at Surf.
6. Install dry hole marker 10-24-03



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER / SUNSET DATE 10/24/03

Type or print name Timothy BAGLEY Telephone No. 432 561-8600
(This space for State use)

APPROVED BY [Signature] TITLE OC FIELD REPRESENTATIVE II / STAFF MANAGER
Conditions of approval, if any: NOV 18 2003