

Submit 3 Copies to appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Pecos Rd., Zia, NM 87041
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. <input checked="" type="checkbox"/> 30-025-21070
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name LEA KN STATE
8. Well Number 2
9. OGRID Number 162738
10. Pool name or Wildcat Midway Abo

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Michael L Pierce	
3. Address of Operator PO Box 16555 Albuquerque New Mexico 87191	
4. Well Location Unit Letter B : 990 feet from the North line and 1650 feet from the East line Section 17 Township 17S Range 37E NMPM LEA County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Spot 35 SX plug on CIBP @ 6850' - CIRC. MLF
Spot 50 SX plug across SAN ANDRES perms @ 5071-5082 - WOC + TAG
Spot 35 SX plug across 8 5/8 casing shoe @ 4299'. 50 foot in and Tag
Spot 35 SX plug @ Base of Salt @ 3210'
Spot 35 SX plug @ Top of Salt @ 2045' - Perf. + Squeeze, WOC + TAG
Perf 5 1/2 casing @ 500' squeeze with 50 SXS - WOC + TAG @ 294' or ABOVE.
Spot 60' surface plug

The Oil Conservation Division **Must be notified**
24 hours prior to the beginning of plugging operations

Will notify OCD prior to commencement of operations.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

Type or print name

E-mail address:

PHONE:

For State Use Only

OCD FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

RECEIVED

OCT 16 2008

HOBBS (11)

Michael L. Pierce

PO Box 16555

Albuquerque, New Mexico 87191-6555

505-856-1213

505-948-0545

October 15, 2008

OIL CONSERVATION DIVISION

1625 N. FRENCH DRIVE

HOBBS, NEW MEXICO 88240

ATTN: Mr. Buddy Hill

RE: P&A Lea KN State # 2 well

Buddy:

As per our conversation on September 4, 2008 please find enclosed the C-103 concerning the above captioned well. I believe that the plugging detail is what you and I had discussed. I am in the process of finding a plugger to do the work. I will keep you advised.

Thank you for your assistance.

Regards,



Michael L Pierce