

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-29247
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 23502
7. Lease Name or Unit Agreement Name Morris
8. Well Number 1
9. OGRID Number 34703
10. Pool name or Wildcat Tatum Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
State of NM, Formerly Saba Energy of Texas Inc.

3. Address of Operator
1625 N. French Drive Hobbs, NM 88240

4. Well Location

Unit Letter D : 660 feet from the North line and 660 feet from the West line
Section 8 Township 13S Range 36E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☒

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Set CIBP @ 10650' and set 25 sxs cement on top
Circ. Hole with fresh water gel
Cut casing @ 7500' did not move
Cut casing @ 4460' and lay down casing
Attempt to circ around casing left in hole. Press to 1000 psi on 8 5/8" and got no circ.
Spot 25 sxs cement @ 7500' WOC and tag @ 7410'.
Spot 35 sxs cement @ 4540' and WOC and tag @ 4270'
Spot 35 sxs @ 3180'
Spot 35 sxs @ 2150'
Spot 35 sxs @ 495' WOC and tag @ 365'
Spot 100' surface plug
Cut off wellhead and set dryhole marker and clean loc for final inspection

RECEIVED
OCT 28 2008
HOBBS OIL

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE [Signature] TITLE _____ Agent _____ DATE 10-26-08

Type or print name Devin Garner E-mail address: garneroil@yahoo.com Telephone No. (575) 631-4770

For State Use Only

APPROVED BY: [Signature] TITLE _____ DATE _____

Conditions of Approval (if any):

GC FIELD REPRESENTATIVE II/STAFF MANAGER OCT 28 2008