

Submit 3 Copies (to Appropriate District Office)
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

WELL API NO. 30-025-35131
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: WAREHOUSE 10
8. Well Number 2
9. OGRID Number 147179
10. Pool name or Wildcat LOVINGTON; UPPER PENN; NORTHEAST

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/>	2. Name of Operator CHESAPEAKE OPERATING, INC.
3. Address of Operator P.O. Box 18496, Oklahoma City, OK 73154-0496	4. Well Location Unit Letter <u>B</u> : <u>1096'</u> feet from the <u>NORTH</u> line and <u>2444</u> feet from the <u>EAST</u> line Section <u>10</u> Township <u>16 S 36</u> Range <u>E</u> NMPM County <u>LEA</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input checked="" type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10-6-08 Set 5 1/2" CIBP @11,642'. 10-8-08 Cap 5 1/2" CIBP w/25 sx. Est. T.O.C. @11,416'. Spot 25 sx. cmt. @9,928'. Est. T.O.C. @9,696'. Spot 25 sx. cmt. @ 8,228'. Est. T.O.C. @8,016'. Spot 25 sx. cmt. @5,300'. Est. T.O.C. @5,041'. Spot 25 sx. cmt. @4,390'. Tag cmt. plug @4,224'. 10-9-08 Perf. @2,175'. Sqz. 50 sx. Pkr. @1,775'. Tag & plug @1,907'. 10-10-08 Perf @483'. Pkr. @60'. Sqz. 60 sx. cmt. W.O.C. & tag plug @276'. Tag plug @276'. Perf. @76'. Circulate 40 sx. cmt. to surface down 5 1/2" csg. X 9 5/8" Csg. 10-10-08 Clean location & install Dryhole Marker.

P & A DATE: 10-10-08

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Randall Minear TITLE P & A SUPERV. DATE 10-15-08
E-mail address: _____

Type or print name RANDALL MINEAR

Telephone No. (432) 530-0569

For State Use Only

APPROVED BY [Signature] TITLE _____ DATE _____

Conditions of Approval, if any:

OCD FIELD REPRESENTATIVE / STAFF MANAGER

OCT 31 2008