. /	
Submit 3 Copies to appropriate District State of New Mexico Office Energy, Minerals and Natural Resources	Form C-103 May 27, 2004
District I 1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II OC 292003 OIL CONSERVATION DIVISION	<u>30-041-20792</u> 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE STATE SEE
1000 Rio Brazes Roll Azire, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. VA 2577
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name: STATE ''BF''
PROPOSALS.) 1. Type of Well:	8. Well Number
Oil Well Gas Well Other x	9. OGRID Number
2. Name of Operator OGS OPERATING CO., INC.	16367
3. Address of Operator	10. Pool name or Wildcat
550 W. Texas, Suite 1140, Midland, TX 79701	
4. Well Location	
Unit Letter <u>A</u> : 660 feet from the <u>NORTH</u> line and	feet from the line
Section 2 Township 8 S Range 36 E	
11. Elevation (Show whether DR, RKB, RT, GR, e 4,089 GR	tc.)
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Di	stance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Constructi	
12. Check Appropriate Box to Indicate Nature of Notice NOTICE OF INTENTION TO: SUE PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	, Report, or Other Data BSEQUENT REPORT OF: ALTERING CASING
NOTICE OF INTENTION TO: SUE	ALTERING CASING .
NOTICE OF INTENTION TO: SUE	ALTERING CASING .
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB	ALTERING CASING .
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and gives of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion.         10-2-08       Notify N.M.O.C.D., Maxey Brown.         10-6-08       Set C.I.B.P. @4,460' w/2 sx. cmt 4,460'-4,430'.	ALTERING CASING ABANDONMENT
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion.         10-2-08       Notify N.M.O.C.D., Maxey Brown.         10-2-08       Notify N.M.O.C.D., Maxey Brown.         10-6-08       Set C.I.B.P. @4,460' w/2 sx. cmt 4,460'-4,430'.         10-7-08       Circulate 10# M.L.F.       Cut 4 1/2" csg. #3,600'.         10-9-08       Pull 3,600' csg. Spot 60 sx. cmt. w/2% CaCl @4,050'. W.O.C.	ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING ADDONMENT
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion.       10-2-08         Notify N.M.O.C.D., Maxey Brown.       10-6-08       Set C.I.B.P. @4,460' w/2 sx. cmt 4,460'-4,430'.         10-7-08       Circulate 10# M.L.F.       Cut 4 1/2" csg. #3,600'.	ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING ADDONMENT ALTERING OPNS. ALTERING OPNS. ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING OPNS. ALTERING OPNS. ALTERING OPNS. ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTE
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion.         10-2-08       Notify N.M.O.C.D., Maxey Brown.         10-6-08       Set C.I.B.P. @4,460' w/2 sx. cmt 4,460'-4,430'.         10-7-08       Circulate 10# M.L.F. Cut 4 1/2" csg. #3,600'.         10-9-08       Pull 3,600' csg. Spot 60 sx. cmt. w/2% CaCl @4,050'. W.O.C. cmt. @2,300'-2,183'. Spot 40 sx. cmt. 60'- surface. Remove	ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING OPN
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion.       OTHER:         10-2-08       Notify N.M.O.C.D., Maxey Brown.       OT-4,430'.         10-6-08       Set C.I.B.P. @4,460' w/2 sx. cmt 4,460'-4,430'.         10-7-08       Circulate 10# M.L.F. Cirt 4 1/2" csg. #3,600'.         10-9-08       Pull 3,600' csg. Spot 60 sx. cmt. w/2% CaCl @4,050'. W.O.C. cmt. @2,300'-2,183'. Spot 40 sx. cmt. @450'.         10-10-08       Tag T.O.C. @320'. Circulate 20 sx. cmt. 60'- surface. Remove P & A Marker. Back fill collar.	ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING ABANDONMENT ALTERING OPNS. ALTERING OPNS. ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING OPNS. ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion.       OTHER:         10-2-08       Notify N.M.O.C.D., Maxey Brown.       OT-08         10-6-08       Set C.I.B.P. @4,460' w/2 sx. cmt 4,460'-4,430'.       OT-09-08         10-7-08       Circulate 10# M.L.F. Cutt 4 1/2" csg. #3,600'.       NO.C. cmt. @2,300'-2,183'. Spot 40 sx. cmt. @450'.         10-10-08       Tag T.O.C. @320'. Circulate 20 sx. cmt. 60'- surface. Remove P & A Marker. Back fill collar.       P & A DATE: 10-1         Thereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit       SIGNATURE       P & A	ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING ABANDONMENT ALTERING OPNS. ALTERING OPNS. ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING OPNS. ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion.       OTHER:         10-2-08       Notify N.M.O.C.D., Maxey Brown.       0-6-08       Set C.I.B.P. @4,460' w/2 sx. cmt 4,460'-4,430'.         10-7-08       Circulate 10# M.L.F.       Cut 4 1/2" csg. #3,600'.       0.0.0.0.0.0.         10-9-08       Pull 3,600' csg. Spot 60 sx. cmt. w/2% CaCl @4,050'. W.O.C. cmt. @2,300'-2,183'. Spot 40 sx. cmt. @450'.       0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.	ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING ALTERING CASING ALTERING A
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion.       OTHER:         10-2-08       Notify N.M.O.C.D., Maxey Brown.       OTHER:         10-6-08       Set C.I.B.P. @4,460' w/2 sx. cmt 4,460'-4,430'.         10-7-08       Circulate 10# M.L.F. Cut 4 1/2" csg. #3,600'.         10-9-08       Pull 3,600' csg. Spot 60 sx. cmt. w/2% CaCl @4,050'. W.O.C. cmt. @2,300'-2,183'. Spot 40 sx. cmt. @450'.         10-10-08       Tag T.O.C. @320'. Circulate 20 sx. cmt. 60'- surface. Remove P & A Marker. Back fill collar.         P & A DATE: 10-1         Thereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines ageneral permit         SIGNATURE       SIGNATURE       TITLE       P & Z         Type or print name       RANDALL MINEAR       TITLE       P & Z	ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING ALTERING ALTERING CASING ALTERING
NOTICE OF INTENTION TO:       SUE         PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILL         PULL OR ALTER CASING       MULTIPLE COMPLETION       CASING TEST AND CEMENT JOB         OTHER:       OTHER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion.       OTHER:         10-2-08       Notify N.M.O.C.D., Maxey Brown.       OTHER:         10-7-08       Circulate 10# M.L.F. Cut 4 1/2" csg. #3,600'.       O.C.         10-9-08       Pull 3,600' csg. Spot 60 sx. cmt. w/2% CaCl @4,050'. W.O.C.       cmt. @2,300'-2,183'. Spot 40 sx. cmt. @450'.         10-10-08       Tag T.O.C. @320'. Circulate 20 sx. cmt. 60'- surface. Remove P & A Marker. Back fill collar.       P & A DATE: 10-1         Thereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines	ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ALTERING OPNS. ALTERING OPNS. ALTERING OPNS. ALTERING OPNS. ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING ALTERING ALTERING OPNS. ALTERING ALTERING ALTERING OPNS. ALTERING ALTERI