



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Field Inspection Program

"Preserving the Integrity of Our Environment"

10-Nov-08

FINLEY RESOURCES INC

1308 LAKE STREET #200

FT WORTH TX 76102

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

STATE E 28 No.002		K-28-20S-36E		✓ 30-025-04360-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By: Inspection No.
11/10/2008	Routine/Periodic	Mark Whitaker	Yes	No	12/15/2008 iMAW0831555124
Violations					
Absent Well Identification Signs (Rule 103)					

Comments on Inspection: No well Sign (Rule 103). New well signs have not been installed. Failure to comply could result in monetary penalties being assessed. 2nd letter of non-compliance.

STATE E 28 No.004		L-28-20S-36E		✓ 30-025-04362-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By: Inspection No.
11/10/2008	Routine/Periodic	Mark Whitaker	Yes	No	12/15/2008 iMAW0831555449
Violations					
Absent Well Identification Signs (Rule 103)					

Comments on Inspection: No well Sign (Rule 103). New well signs have not been installed. Failure to comply could result in monetary penalties being assessed. 2nd letter of non-compliance.

MAGRUDER STATE No.002

J-28-20S-36E ✓ 30-025-04364-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
11/10/2008	Routine/Periodic	Mark Whitaker	Yes	No	12/15/2008	iMAW0831555683

Violations

Absent Well Identification Signs (Rule 103)

Comments on Inspection: No well Sign (Rule 103). New well signs have not been installed. Failure to comply could result in monetary penalties being assessed. 2nd letter of non-compliance.

STATE E 33 No.001

C-33-20S-36E ✓ 30-025-04379-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
11/10/2008	Routine/Periodic	Mark Whitaker	Yes	No	12/15/2008	iMAW0831555816

Violations

Absent Well Identification Signs (Rule 103)

Comments on Inspection: No well Sign (Rule 103). New well signs have not been installed. Failure to comply could result in monetary penalties being assessed. 2nd letter of non-compliance.

STATE E 33 No.002

D-33-20S-36E ✓ 30-025-04380-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
11/10/2008	Routine/Periodic	Mark Whitaker	Yes	No	12/15/2008	iMAW0831555975

Violations

Absent Well Identification Signs (Rule 103)

Comments on Inspection: No well Sign (Rule 103). New well signs have not been installed. Failure to comply could result in monetary penalties being assessed. 2nd letter of non-compliance.

STATE E 33 No.003

F-33-20S-36E ✓ 30-025-04381-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
11/10/2008	Routine/Periodic	Mark Whitaker	Yes	No	12/15/2008	iMAW0831556071

Violations

Absent Well Identification Signs (Rule 103)

Comments on Inspection: No well Sign (Rule 103). New well signs have not been installed. Failure to comply could result in monetary penalties being assessed. 2nd letter of non-compliance.

STATE SPX No.004

G-33-20S-36E ✓ 30-025-04389-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
11/10/2008	Routine/Periodic	Mark Whitaker	Yes	No	12/15/2008	iMAW0831556181

Violations

Absent Well Identification Signs (Rule 103)

Comments on Inspection: No well Sign (Rule 103). New well signs have not been installed. Failure to comply could result in monetary penalties being assessed. 2nd letter of non-compliance.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,


COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER

017H15554612

\$0.420

11/10/2008

Mailed From 88240

US POSTAGE

FINLEY RESOURCES INC
1308 LAKE STREET #200
FT WORTH, TX 76102