Submit 3 Copies To Appropriate District State of New Mexico Energy, Minerals and Natural Resources	Form C-103 May 27, 2004
District I 1625 N. French Dr. Hopes, NM 87240 District II ONLY CONSERVATION DIVISION	WELL API NO.
	30-025-34854 ✓ 5. Indicate Type of Lease
1301 W Grand Ave , Artesia, NM 88210 District HL 19 1000 Rio Biazos Rd, Azieca NM 887410 Santa Fe, NM 87505	STATE X FEE
District Ly	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	o. State on a cas heart ive.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name: RANCHO VERDE 10 STATE
PROPOSALS.) 1. Type of Well:	8. Well Number
Oil Well 🗵 Gas Well 🗌 Other	3
2. Name of Operator	9. OGRID Number
NEARBURG PRODUCING COMPANY 2. Address of Operator	015742 10. Pool name or Wildcat
3. Address of Operator 3300 N. A ST. BLDG. 2, STE 120, MIDLAND, TX 79705	ANDERSON RANCH; WOLFCAMP, SW
4. Well Location	
Unit Letter F: 2310 feet from the NORTH line and 1810 feet from the WEST line	
Section 10 Township 16 S Range 32 E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, et 4317	c.)
Pit or Below-grade Tank Application or Closure	
Pit type STEEL Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	ING OPNS. PLUG AND X X ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	Approved for plugging of well bore only. Liability under bond is retained pending receipt
1	of C-103 (Subsequent Report of Well Plugging)
	which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
10-13-08 Notify N.M.O.C.D., Maxey Brown. 10-14-08 Unable to establish PIR under pkr. @5,546'. Set 5 1/2" CIBP @5,700', per O.C.D. Maxey Brown. 10-15-08 Tag B.P. @5,700'. Circulate 10# M.L.F. Spot 25 sx. cmt. & cut 5,700'-5,448'. Cut 5 1/2" csq. @5,400'. Unable to pull csq. from 5,400'. 10-16-08 Cut & pull 5 1/2"	
csg. from 5,200'. 10-20-08 Spot 50 sx. cmt. @5,450'. W.O.C. & tag T.	•
04,300' w/2% CaCl. 10-21-08 Tag T.O.C. 04,178'. Spot 35 sx. cmt 1,500'-1,371'. Spot 50 sx. cmt. with	
2% CaCl @514'. W.O.C. & tag T.O.C. @343'. Circulate 20 sx. cmt 60	·
anchors. Install P & A Marker. Backfill collar.	
P & A DATE: 10-21-	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permitor an (attached) alternative OCD-approved plan	
SIGNATURE TITLE P & I	A SUPV. DATE 10-31-08
Type or print name (ARY EGGLESTON Telephone No. (432) 530-0907	
For State Use Only	NOV 13 2008
APPROVED BY TITLE Conditions of Approval, if any	DATE