AFT JENNE .					
Submit 3 Copies To Ap. NOV. 1 8 2008 State of New Mexico Office	Form C-103 May 27, 2004				
District I 1625 N. French Dr., Hophs, NM-87240 District II 1301 W. Grand Asse, Aprelia, NM-87240 1301 W. Grand Asse, Aprelia, NM-87240 1220 South St. Francis Dr.	WELL API NO. 30-025-05491				
	5. Indicate Type of Lease				
1000 Rio Brazos Rd , Aztec, NM 87410 Santa Fe, NM 87505	STATE X FEE				
District IV 1220 S St. Francis Dr , Santa Fe, NM 87505	6. State Oil & Gas Lease No.				
SUNDRY NOTICES AND REPORTS ON WELLS I (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name:				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	North Hobbs G/SA Unit				
PROPOSALS ) 1. Type of Well:	8. Well Number				
Oil Well X Gas Well Other TxA'd	111				
2. Name of Operator	9. OGRID Number				
Occidental Permian Limited Partnership 🖌	157984				
3. Address of Operator	10. Pool name or Wildcat				
P.O. Box 4294, Houston, TX 77210-4294	Hobbs; Grayburg - San Andres				
4. Well Location					
Unit Letter D : feet from the North line and	660 feet from the West line				
Section 25 Township 18-S Range 37-E	NMPM County Lea				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3675' DF					
Pit or Below-grade Tank Application or Closure					
Bit type Depth to Groundwater Distance from nearest fresh water well Dis	tance from nearest surface water				
Pit Liner Thickness:      mil       Below-Grade Tank: Volumebbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data				
	SEQUENT REPORT OF:				

PERFORM REMEDIAL WORK	PLUG AND ABANDON	1	REMEDIAL WORK		ALTERING CASING	
	CHANGE PLANS		COMMENCE DRILLING OPNS.	-	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB			
OTHER: Convert TxA'd oil wel	l to injection	X	OTHER:			

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment

I hereby certify that the information above is true and complete to grade tank has been/will be constructed or closed according to NMOCD gui	o the best of my knowledge and belief. I further certify that idelines X , a general permit or an (attached) alternative O	it any pit or below- CD-approved plan
SIGNATURE Mark Stephen	TITLE Regulatory Compliance Analyst DATE	11/14/08
Type or print name Mark Stephens	E-mail address: Mark_Stephens@oxy.com Telephone No	. (713) 366-5158
For State Use Only APPROVED BY	PETROLEUM ENGINEER	NOV 1 9 2008
Conditions of Approval, if any:		

Page 2 (C-103 Attachment)

Convert TxA'd producer to injection as follows:

1) MI x RU. ND WH x NU BOP.

2) Drill out CIBP at 4054' and CICR at 4020'.

3) Squeeze open perfs at 4087' - 4180' per Halliburton recommendation.

- 4) Drill out to 4190' x test squeeze to 1000 psi.
- 5) Deepen well to 4350'.
- 6) Run CNL/CCL/GR from new TD to 3000'.

7) Run 4-1/2" FJ liner from 4000' to TD x cement in place.

- 8) Perf x stimulate based on new log data.
- 9) Pump scale squeeze.
- 10) RIH with 4-1/2" packer on new Duo-line injection tubing (set packer at +/- 4105').
- 11) Pressure test casing x chart for the NMOCD.
- 12) ND BOP x NU WH. \*Turn well over to injection.
- 13) RD x MO x clean location.

\*Note: Injection will not commence until Form C-108 has been approved by the NMOCD.