Submit 3 Copies To Appropriate District Office State of	New Mexico	F C 102
District I Energy Minerals	and Natural Resources	Form C-103 Revised June 10, 2003
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSER	Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	
	District III	
District IV Santa F	District IV Santa Fe NM 87505	
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		BP America
- Not Oblitab.)		
1. Type of Well: Oil Well Gas Well Other		8. Well Number 1
older		
- Control Control		9. OGRID Number 025482
3. Address of Operator P. O. Box 352, Midland, TX 79702		10. Pool name or Wildcat
4. Well Location		Nadine Drinkard Abo
Unit Letter H : 2310 feet from the North line and 990 feet from the East line		
Section 15 Township 1	00 D 200	
Section 15 Township 19S Range 38E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
GR=3597, RKB=3609.5'		
12. Check Appropriate Box to Indicate Nature of Notice Report or Other Data		
NOTICE OF INTENTION TO:	l Sue	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DR	RILLING OPNS.⊠ PLUG AND □
PULL OR ALTER CASING MULTIPLE	☐ CASING TEST A	ABANDONMENT
COMPLETION	CEMENT JOB	
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent details, and give pertinent details.)		
or smaller mily proposed work). SEE RULE 1103. For Militinie Completions. Attach wellhore diagram of monared assembled in		
or recompletion.		
11/18/03 Spud well @ 5:30 AM CST with Key Drilling Rig #6.		
11/19/03 TD 121/4" surface hole @ 1.609'. Circulate hole clean RIH w/37 its 24# L-55 8 5/8" csg. to a setting depth of		
1600' Coment with lead of 650 or Close "6" w/s 1 to 1 w/200 or Close "6" w/20 Close "6" w/200 or Close "6" w		
Plug Down. WOC 8 hrs. Nipple up BOP. Install H2S equipment as per NMOCD orders.		
15 AG 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		
		(1) L. S. J. L. J. L. S. J. L. J. L. J. J. L. J. L. J. L. J. L. J. J. L. J. J. L. J. J. J. J. J. J. J.
		(T T T T T T T T T T T T T T T T T T T
		E E
	•	O Solver S
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE My Caw and	TITLE Production A	malyst DATE 11/21/03
Type or print name	ACrawford	@xericoil.com 432-683-3171
(This space for State use)	E-mail address:	Telephone No.
	TOICT SI IPEDVISAD/CENIES	RAL MANAGER
APPPROVED BY Chris Williams	TITLE BUILTING	D-A-72€ ∧ 1 2002
Conditions of approval, if any:		JEC O - L ZOUS