

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N.M. Oil Cons. Division
1625 N. French Dr.
Hobbs, NM 88240

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side


1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Serial No. LC-032096-A
2. Name of Operator APACHE CORPORATION	6. If Indian, Allottee or Tribe Name
3a. Address TWO WARREN PLACE, SUITE 1500 6120 S. YALE TULSA, OK 74136	7. If Unit or CA/Agreement, Name and/or No.
3b. Phone No. (include area code) (918) 491-4900	8. Well Name and No. LOCKHART A-17 #7
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SEC. 17-T21S-R37E 2630' FSL, 990' FEL	9. API Well No. 30-025-36159
	10. Field and Pool, or Exploratory Area PENROSE SKELLY; GRAYBURG
	11. County or Parish, State LEA

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other SPUD; SET SURF
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	CSG; TD; SET PROD
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	CSG.

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

PLEASE SEE ATTACHED DRILLING HISTORY.



14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) LARRY E. RADER		Title TECHNICAL COORDINATOR - DRILLING
Signature <i>Larry E. Rader</i>		Date 2/28/03
THIS SPACE FOR FEDERAL OR STATE OFFICE USE		

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

OPERATOR: APACHE CORPORATION
WELL: LOCKHART A-17 #7
API# 30-025-36159
LEASE S/N: LC-032096-A

2/16/2003 MIRU CAPSTAR RIG #8. DRILL & SURVEY TO 412'. RIH W/ 8-5/8" 24# J55 ST&C CASING W/5 CENTRALIZERS. CEMENT SHOE AT 412' W/ 325 SX CLASS C + 2% CACL + 0.125 #/SX CELLO FLAKE=78 BBLS 14.8 PPG SLURRY, YIELD=1.34 CF/SX. DISPLACE PLUG--CIRC 76 SX CMT TO PIT. WOC.

2/17/2003 - 2/20/03 DRILL & SURVEY 412' - 3785'.

2/21/2003 DRILL 3785' - 4100'. RAN LOGS. STARTED RUNNING 5-1/2" CASING.

2/22/2003 RIH W/ 5 1/2" 17# J55 LT&C CSG. W/ 17 CENTRALIZERS. CEMENT SHOE @4100' W/500 SX 50:50 POZ:CLASS C W/ 10% GEL + 5% SALT + 0.125 #/SX CELLO FLAKE + 0.003 GPS FP-6L=217 BBLS 11.8 PPG SLURRY, YIELD= 2.44 CF/SX. TAIL W/ 250 SX 50:50 POZ:CLASS C W/ 2% GEL + 5% SALT + 0.003 GPS FP-6L=57 BBLS 14.2 PPG SLURRY, YIELD=1.29 CF/SX. CIRC 105 SX CMT TO PIT. RELEASE RIG @9:30 AM 2/22/03

LOCKHART A-17 #7
FILED
FEB 23 2003
OCC