

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis, Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	WELL API NO. 30-025-24005
2. Name of Operator Saga Petroleum LLC	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator 415 W. WALL ST. SUITE 1900 MIDLAND, TX 79701	6. State Oil & Gas Lease No. B-2656
4. Well Location Unit Letter <u>O</u> : 688 feet from the <u>S</u> line and 2111 feet from the <u>E</u> line Section 33 Township 18S Range 38E NMPM County LEA	7. Lease Name or Unit Agreement Name CONOCO STATE
	8. Well Number 4
	9. OGRID Number 148967
	10. Pool name or Wildcat HOBBS DRINKARD
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: Add perfs <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Intend to perforate the Tubb formation from 6412'-6495' & 6504'-6598' (181 holes), Possible Otis WB pkr @ 6858'.
RIH w/7" Model R pkr on tbg to 6600', test tbg to 6000 psi,
Acidize well w/1500 gal 15% NEFE & 5000 gal 15% Ultragel acid in 3 stages, drop 500 1.3 SG balls between stages @ 7 BPM & 5000 psi max press. Swab back load
Test produce Tubb perfs until production stabilized.
Unset pkr & DHC Drinkard & Tubb perfs



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 11/25/2003

Type or print name Bonnie Husband Telephone No. (432)684-4293

(This space for State use)

APPROVED BY Gay W. Winter FIELD REPRESENTATIVE II/STAFF MANAGER DATE DEC 03 2003
Conditions of approval, if any: