Submit 3 Copies_To Appropriate District State of New Mexico	Form C-103
Submit 3 Copies_To Appropriate Provided State of New Mexico Office District I	May 27, 2004 WELL API NO.
District I 1625 N. French Dr., Hobbs, NM 87240 District II JAN Z 6 OIL CONSERVATION DIVISION 1301 W Grand Ave., Artesia, NM 88210 1220 South St. Francis Dr.	WELL API NO.  30-025-28990
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztac, 1000 Santa Fe, NM 87505	STATE 🗹 FEE 🗌
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 29797
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name:
PROPOSALS.)  1. Type of Well:  Oil Well  Gas Well  Other xx	8. Well Number
2. Name of Operator	9. OGRID Number
CHAMPLIN EXPLORATION, INC.	53454
3. Address of Operator	10. Pool name or Wildcat
P.O. BOX 3488, eNID, ok 73702	Grama Ridge Wolfcamp North Gas
4. Well Location	
Unit Letter K: 1980feet from theSOUTHline and	2310 feet from the WEST line
Section 20 Township 21 S Range 35 E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, et 3,624.5 GR	c.)
Pit or Below-grade Tank Application or Closure	
Pit type STEEL Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice,  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK	Report, or Other Data SEQUENT REPORT OF:  ALTERING CASING
TEMPORARILY ABANDON	ING OPNS. PLUG AND X
PULL OR ALTER CASING	
li	pproved for plugging of well bore only. ability under bond is retained pending receipt
OTHER: Of OTHER: of well	C-103 (Subsequent Report of Well Plugging)
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent details, and give pertinent details, and give pertinent details, and give pertinent details. See a starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
12-11-08 Notify NMCCD, Mark Whitaker. 12-19-08 Purge 700 sx cmt. under pkr. @4,000'. Displace T.O.C. to 4,100'. 12-22-08 Tag T.O.C. @4,055'. Circulate 10# M.L.F. Cut 5 1/2" csg. @4,043'. 12-24-08 Spot 50 sx.	
cmt. w/2% CaCl 04,055'. W.O.C. & tag 03,923'. Perf. 03,490'. Spot 50	
@3,352'. Cut 5 1/2" csg. @2,250'. 12-31-08 Spot 50 sx. cmt. w/2% CaCl @2,300'. W.O.C. & tag T.O.C.	
02,170' Spot 80 sx. 01,620'. 1-5-09 Tag T.O.C. 01,475'. Spot 70 sx. cmt. 500'- 394'. Circulate 40 sx.	
60'-surface. Remove wellhead & anchors. Install P & A marker. Backf	fill ∞llar.
P & A DATE: 1-5-09	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been with be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan	
SIGNATURE RANGOLL / WILLOW TITLE PEA	A SUPV. DATE 1-14-09
Type or print name RANDALL MINEAR  E-mail address:	Telephone No. (432) 530-0907
For State Use Only  DISTRICT 1	SUPERVISOR IAN 2 7 200
APPROVED BY One TITLE TITLE Conditions of Approval, if any:	DATE