

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico

Minerals and Natural Resources

Form C-103

May 27, 2004

RECEIVED

JAN 30 2009

CONSERVATION DIVISION
1220 South St. Francis Dr.
HOBBS
Santa Fe, NM 87505

WELL API NO.

30-025-09291

5. Indicate Type of Lease

STATE ☒ FEE ☐ ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

State A A/C 1

8. Well Number 38

9. OGRID Number

194849

10. Pool name or Wildcat

Jalmat Tansill Yates 7 rvrs (Gas) 79240

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☒

2. Name of Operator

Petrohawk Operating

3. Address of Operator

1000 Louisiana, Suite 5600 Houston TX 77002

4. Well Location

Unit Letter M : 990 feet from the South line and 990 feet from the West line
Section 10 Township 23S Range 36E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
GL-3450'

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: TA Test ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Test Date: 1-29-09

1. Load casing with packer fluid. (CIBP @ 2850')
2. Pressure test casing: surface to 2850' to 545# for 30 minutes. Bradenhead neutral during test.
3. Record test on chart. (OCD rep. Mark Whitaker witness test). See attached chart.
4. Request TA status for 5 years.

This Approval of Temporary
Abandonment Expires 2-3-2014

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Joel Sisk TITLE Production Foreman DATE 1-29-09

Type or print name Joel Sisk

E-mail address: jsisk@petrohawk.com

Telephone No. 575-394-2574

For State Use Only

APPROVED BY: [Signature] TITLE DISTRICT 1 SUPERVISOR DATE FEB 03 2009

Conditions of Approval (if any):

