## RECEIVED

(Instructions on page 2)

Form 3160 FEB 0 3 2(11)9 UNITED STATES DEPARTMENT OF THE INTERIOR FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 HOBBSOCD UREAU OF LAND MANAGEMENT 5. Lease Serial No. LC032573B SUNDRY NOTICES AND REPORTS ON WELLS If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well Gas Well□□ 8. Well Name and No. Elliott B Federal #20 2. Name of Operator Range Operating New Mexico, Inc. API Well No. 30-025-39023 3b. Phone No. (include area code) 3a. Address 817-869-4216 100 Throckmorton St., Ste. 1200, Fort Worth, TX 76102 10. Field and Pool, or Exploratory Area Blinebry, Tubb, Drinkard, Wantz; Abo 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 930' FSL & 2310' FEL, Unit O, Sec. 6, T22S, R37E Lea 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Water Shut-Off Production (Start/Resume) Deepen Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other Injection Interval Casing Repair New Construction Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Test Final Abandonment Notice Plug Back Convert to Injection Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) RIH and set RBP @ 3000'. Fill 5.5" with 2% KCl water. MIRU wireline unit to run temperature survey while injecting. Hook up to surface casing/production casing annulus (bradenhead valve) and begin injecting 10# brine and establish injection and rate (not to exceed 1800 psi and/or 3 bpm). Once injection rate and pressure have been established, run temperature survey. SD injection and POOH w/survey. Evaluate survey for injection interval. Approval Subject to like from State OCD APPROVED FEB 1 2009 JAMES A. AMOS SUPERVISOR-EPS I bereby certify that the foregoing is true and correct Name (Printed/Typed) Paula Nale Title Sr. Reg. Sp. Signature 01/23/2009 Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE arus 2 Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.