

Submit 3 Copies To Appropriate District Office  
District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Minerals and Natural Resources

Form C-103  
June 19, 2008

RECEIVED

FEB 25 2009

MOBBSOCD

CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <input checked="" type="checkbox"/> 30-025-20673
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name VACUUM GLORIETA WEST UNIT <input checked="" type="checkbox"/>
8. Well Number 8 <input checked="" type="checkbox"/>
9. OGRID Number 4323 <input checked="" type="checkbox"/>
10. Pool name or Wildcat VACUUM GLORIETA <input checked="" type="checkbox"/>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
CHEVRON U.S.A. INC. ☒

3. Address of Operator  
15 SMITH ROAD, MIDLAND, TEXAS 79705

4. Well Location

Unit Letter O: 510 feet from the SOUTH line and 1980 feet from the EAST line ☒

Section 24 Township 17-S Range 34-E NMPM County LEA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: INTENT TO TEMPORARILY ABANDON

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

CHEVRON U.S.A. INC. INTENDS TO TEMPORARILY ABANDON THE SUBJECT WELL BY REMOVING THE PUMPING EQUIPMENT. THE INTENDED PROCEDURE IS AS FOLLOWS:

1) NOTIFY NMOCD. 2) MIRU. 3) KILL WELL. 4) NDWH. NUBOP. 5) PULL RODS. 6) LD RODS & PUMP. 7) RUN SCRAPER. 8) SET CIBP @ 5900. 9) CIRC PKR FLUID & PRETEST TO 500 PSI. 10) NDBOP. NUWH. 11) NOTIFY NMOCD. 12) CHART & TEST. 13) RIG DOWN. *<100' top Parts*

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Denise Pinkerton* TITLE REGULATORY SPECIALIST DATE 02-23-2009

Type or print name DENISE PINKERTON E-mail address: [leakejd@chevron.com](mailto:leakejd@chevron.com) PHONE: 432-687-7375

For State Use

APPROVED BY: *Tammy L. Hill* TITLE DISTRICT 1 SUPERVISOR DATE FEB 26 2009

Conditions of Approval (if any):

Condition of Approval : Notify OCD Hobbs  
office 24 hours prior to running MIT Test & Chart