Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resour	rces May 27, 2004
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1301 W. Grand Ave., Artesia, NM 88210 District III 1301 South St. Francis Dr.		WELL API NO. 30-025-09200
1301 W. Grand Ave., Artesia, NM 88210		5. Indicate Type of Lease
District IV NM 87410 MAR 0 2 711220 South St. Francis Dr. Santa Fe, NM 87505		STATE FEE
District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM HO 87505	3B20CD	26711
SUNDRY NOTIC	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.)		King "C" 8. Well Number 2
1. Type of Well: Oil Well Gas Well Other		
2. Name of Operator		9. OGRID Number 002799
Breck Operating Corp. 3. Address of Operator		10. Pool name or Wildcat
P.O. Box 911, Breckenridge, Texas 7624		Langlie Mattix 7 Rvrs Q-Graysburg
4. Well Location		
	0 feet from the North line and 231	0 feet from the East line
		6E NMPM Lea County
Section 1	11. Elevation (Show whether DR, RKB, RT,	
	3427' RKB	Ori, etc.)
it or Below-grade Tank Application 🗌 or		I A SA SAMMAN AND A
it type <u>Steel</u> Depth to Groundwater_	300' Distance from nearest fresh water well >10	000' Distance from nearest surface water >1000'
t Liner Thickness: mil		bbls; Construction Material
	opropriate Box to Indicate Nature of N	Notice Report or Other Data
12. CHECK A	propriate box to indicate Nature of i	votice, report of other Bata
NOTICE OF INT	ENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIA	AL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS COMMEN	NCE DRILLING OPNS.□ P AND A □
PULL OR ALTER CASING	MULTIPLE COMPL	CEMENT JOB
		To a constitut Alexander
OTHER:	OTHER:	Temporarily Abandon tails, and give pertinent dates, including estimated date
of starting any proposed wor	k) SEE RULE 1103. For Multiple Complet	ions: Attach wellbore diagram of proposed completion
or recompletion.		3 1 1 1
•		
C dl. to Towns anguile. A bom	don the well	
erformed work to Temporarily Aban alled NMOCD and received procedu		
	x plug across perforations (3568'-3713').	
	imp another 25 sx plug. RIH and tag plug at 3	3453'.
20/09 John R. Harrison w/NMOCD	witnessed successful MIT. Starting pressure	e 560 psig. After 40 minutes pressure was 560 psig.
Chart is attached.		
	TTI I A I C T	
	this Approval of I	emporary bires 2-20-20H
	Abandonment Exp	of the second se
nereby certify that the information a	bove is true and complete to the best of my k	nowledge and belief. I further certify that any pit or below-
ade tank has been will be constructed or c	losed according to NMOCD guidelines 🔼, a general	permit ☐ or an (attached) alternative OCD-approved plan ☐.
ICHATURE & ball &	TITLE Vice Persi	dent / Production Mar. DATE January 26 2000
IGNATURE / Lius / L	TITLEVICE-Presion	dent / Production Mgr. DATE January 26, 2009
ype or print name Daniel D. Wilso	on E-mail address: dwilson@breckop	.com Telephone No. 254-559-3355 ext 233
or State Use Only		
PPROVED BY:	TITLE DISTRIC	T 1 SUPERVISOR DATE MAR 0 3 20

Conditions of Approval (if any):



