

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-29872 ✓
5. Indicate Type of Lease STATE ☐ FEE ☒ ✓
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name J.A. Akens ✓
8. Well Number 14 ✓
9. OGRID Number 147179 ✓
10. Pool name or Wildcat Hardy; Drinkard-Tubb

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator Chesapeake Operating, Inc.

3. Address of Operator P.O. Box 18496
Oklahoma City, OK 73154-0496

4. Well Location
Unit Letter W : 907' feet from the South line and 1650' feet from the East line
Section 3 Township 21S Range 36E NMPM County Lea ✓

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3565' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	P AND A ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB ☐	
DOWNHOLE COMMINGLE ☐			
OTHER: ☐		OTHER: ☐	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Chesapeake Operating, Inc. respectfully request to plug and abandon this well.

Please find attached the plugging procedure, the actual and proposed well bore diagram and NMOCD's C-144 (CLEZ) pit permit.

RECEIVED

MAR 05 2009

HOBBSOCD

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Bryan Arrant

TITLE

DATE 03/04/2009

Type or print name Bryan Arrant

E-mail address: bryan.arrant@chik.com

PHONE: (405)935-3782

For State Use Only

APPROVED BY:

Cary W. Hill

TITLE

DISTRICT 1 SUPERVISOR

DATE

MAR 05 2009

Conditions of Approval (if any):

THE OIL CONSERVATION DIVISION **MUST**
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS

**J A Akens 14-3
Lea County, New Mexico
Plugging Procedure**

Date: March 4, 2009

Location: 907' FSL & 1650' FEL Sec. 3, 21S-36E

Production Casing: 5 1/2" 14# & 15.5# Liner set at 7000'

PBTD/TD: 6800' / 7000'

Current Perfs: 6581' -6778' Drinkard

Recommended Procedure:

1. MIRU PU. NDWH/NUBOP.
* — *Cap CIRC @ 6800' w/ 35' cmt.*
2. Set CIBP @ 6500' w/ 35' cmt.
3. Fill 5 1/2" Csg with salt gel mud containing 9.5 pound brine and 12.5 lbs of gel per barrel.
4. PUH to 5300'. Set 100 sx plug from 5200'-5300'. Top of Glorieta plug. WOC. Tag plug.
5. PUH to 2750'. Set 100 sx plug from 2650'-2750'. Intermediate Csg plug. WOC. Tag plug.
- * — *Perf. + Squeeze TOS @ 1200', WOC-TAG*
6. PUH to 466' and fill csg back to surf with cement. POH w/ tbg. Top off csg with cmt.
 Perf. csg., Squeeze.
7. RD and move off. Install dry hole marker and cut off dead men. Restore location.

Contacts

Workover Superintendent

Lynard Barrera
Office: 575-391-1462
Cell: 575-631-4942

Asset Manager

Kim Henderson
Office: 405-935-8583
Cell: 405-312-1840

Production Foreman

Ralph Skinner
Office: 575-391-1462
Cell: 575-441-4921



Proposal for Workover

J A AKENS 14-3

Field: HARDY DRINKARD
County: LEA
State: NEW MEXICO
Location: SEC 3, 21S-36E, 907 FSL & 1650 FEL
Elevation: GL 3,553.50 KB 3,565.00
KB Height: 11.50

Spud Date: 3/24/1987
Initial Compl. Date:
API #: 3002529872
CHK Property #: 890342
1st Prod Date:
PBTB: Original Hole - 6800.0
TD: 7,000.0

