Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 June 19, 2008	
1625 N French Dr , Hobbs, N	Energy, Minerals and Natural Resources Hobbs, N. P. C. L.		WELL API NO. /	
OIL CONCEDUATION DIVICION			30-025-39094 5. Indicate Type of	of Lease
District III FEB 2 0 2009 1220 South St. Francis Dr. Santa Fe, NM 87505		icis Dr.	STATE [FEE 🛛
District IV 1220 S St Francis Dr , Santa Fell OBBSOCE 87505	Santa Fe, NM 87	7505	6. State Oil & Gas	s Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name CENTRAL DRINKARD UNIT /	
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other INJECTION			8. Well Number 435	
2. Name of Operator CHEVRON U.S.A. INC.			9. OGRID Numbe	er 4323 /
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705			10. Pool name or Wildcat DRINKARD	
4. Well Location				
Unit Letter D: 660 feet from the		t from the WEST lir NMPM		154
Section 29 Township 21-S Range 37-E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				

12. Check Appropri	ate Box to Indicate N	ature of Notice, R	Report or Other	Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				ALTERING CASING
TEMPORARILY ABANDON				P AND A
DOWNHOLE COMMINGLE	EL COMI E	O/CONTO/OLIVIZITY		
OTHER:	П	OTHER: NEV	V WELL COMPLE	TION
13. Describe proposed or completed ope	rations. (Clearly state all p	pertinent details, and	give pertinent date	es, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
11-13-08: MIRU. TIH W/GR/CCL/CBL TO 6000. 11-18-08: TAG @ 65599. 11-19-08: DRILL OUT CMT 6599-6683.				
11-21-08: TIH W/GR/CCL/CBL TO TAG BTM @ 6683. LOG 6683-SURF. 11-24-08: PERF 6616-26, 6630-36, 6640-48. FRAC 6616-48 W/12 PROPELLANT STICKS. RIG DOWN. 12-19-08: MIRU. 12-22-08: TIH W/BIT & TAG @ 6683. 12-29-08: SET PPI				
TOOLS @ 6638 & 6650. ACIDIZEW 6640-6648 W/420 GALS 15% HCL. ACIDIZE 6630-6636 W/294 GALS 15% HCL. ACIDIZE				
6616-6626 W/504 GALS 15% HCL. PULL PKR TO 6589. SWAB. 12-31-08: SET PKR @ 6546. 1-05-09: ACIDIZE BALL JOB				
W/4000 GALS 20% HCL. 1-06-09: SWAB. REL PKR. 1-07-09: TIH. CIRC 150 BBLS PKR FLUID. 1-08-09: CONDUCT 30 MIN MIT. GOOD. (ORIGINAL CHART & COPY OF CHART ATTACHED). RIG DOWN.				
2-19-09: THERE ARE NO VOLUMES AS OF TODAY. WILL TURN IN WHEN AVAILABLE.				
	 1	<u> </u>	WFY-	<u>8</u> 47
Spud Date:	Rig Release Da	ıte:		
<u> </u>	-		<u></u>	
I hereby certify that the information above is	rue and complete to the be	est of my knowledge	and belief.	
) , ,		•	
SIGNATURE OXIMISE J.M.	er or title RE	EGULATORY SPEC	IALIST DA	TE 02-19-2009
Type or print name DENISE PINKERTON E-mail address: leakejd@chevron.com PHONE: 432-687-7375 For State Use Only				
APPROVED BY: DISTRICT 1 SUPERVISOP DATE MAR 0 9 2009				
Conditions of Approval (if any):				

