Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

MAR U 4 ZHHH

RECEIVED

FORM APPROVED OMB NO. 1004-0137 Expires March 31, 2007

5. Lease Serial No.

NM 19858

HOBRACCD

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well	Па Пол. /	/			8. Well Name	and No.
X Oil Well Gas Well Other					Triste Draw 35 Fed #1	
2. Name of Operate						
EOG Resources Inc. 3a Address 3b. Phone No. (include area code)					9. API Well N	•
3a. Address P.O. Box 2267 Midland, Texas 79702				i la		719
P.O. Box 2	1 (Footage, Sec., T., R., M., or Survey	Description)	432-000-3009		l .	Pool, or Exploratory Area From Spring
	,					
Sec 35, T-24-S, R-33-E 1150 FSL & 600 FWL					11. County of	or Parish, State
TISO PSIL &	OUD FILE				Lea	NM /
12.	CHECK APPROPRIATE	BOY(ES) TO IND	ICATE NATURE OF	NOTICE BEPO		
	PE OF SUBMISSION			PE OF ACTION		
117						
	Notice of Intent	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off
		Alter Casing	Fracture Treat	Reclamatio	n	Well Integrity
x	Subsequent Report	1 =		D Pagamulat	•	Other
		Casing Repair	New Construction	Recomplet		Outer
Final Abandonment Notice		Change Plans	Plug and Abandon	Temporaril	y Abandon	
		Convert to Injection	on X Plug Back	Water Disp	isposal	
	MIRU to prep for recompl Dumped 35' cement on CID	æ.				
	RIH and set 2nd 2.10" CTBP at 12966'. Dumped 45' cement on CTBP. Shut-in, RDMO.					
	MIRU to recomplete. Prep to perforate. Perforate 2-7/8" tubing at 7515' & 7516'. Circulate out heavy mud until clean.					
1/16/09	Perforate 2-7/8" tubing RIH and perforate 2-7/8"				icii ciean	•
1 (15 (00	RIH and periorate 2-7/8				Mortrod '	2_7/8" tubing
1/1//09	no movement.	Cutter at 1020	o. For all lay	COMI CUCCEI.	WOLDON A	z-//o cubing/
1/18/09						
	Pick up power swivel. Pump 2-7/8" tubing out of hole from cut at 10200'. Lay down tubing.					
NAME AND ADDRESS OF THE PARTY O	Trip in hole with 4-3/4" bit and 5-1/2" casing scraper.					
1/20/09	/20/09 Clean out hole to 10198'. RIH w/ 5-1/2" CIBP and set at 10192'. Dump 35' cement on CIBP. POCH.					
1/21/09	Pressure test casing.					
	1/22/09 Perforate from 9475' to 9495', 0.42", 80 holes.					
1/23/09	Perform 1500 gal 15% NEFE acid ball job. Flowback.					
1/24/09	RIH w/ 4" frac liner, TO	ML at 5920', Lin	er set at 6148'.			
14. I hereby certif Name (Printed	fy that the foregoing is true and correct		Title			
Stan Wagner			Regula	atory Analysi	t	
Signature	1	Date 2/25/09	Date 2/25/09			
	Man Wagner	S SDACE FOR FED	ERAL OR STATE OF			
Approved by	<u>/</u> (n):	J JFACE FOR FED	Title	I IOL UJE	Ti	Date
certify that the ap	roval, if any, are attached. Approval opplicant holds legal or equitable title to le the applicant to conduct operations the	those rights in the subj		7		

Form 3160-5 (February 2005)

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED

FORM APPROVED OMB NO. 1004-0137

Expires March 31, 2007 5. Lease Serial No.

Date

SUNDRY NOTICES AND REPORTS					
Do not use this form for proposals to dr abandoned well. Use Form 3160-3 (APD)	ill or to re-enter an 6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instruction	7. If Unit or CA/Agreement, Name and/or No				
1. Type of Well X Oil Well Gas Well Other 2. Name of Operator	8. Well Name and No. Triste Draw 35 Fed. #1				
EOG Resources, Inc.	9. API Well No.				
3a. Address	3b. Phone No. (include area code) 9. APT Well No. 30–025–34719				
P.O. Box 2267 Midland, TX 79702	432-686-3689 10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Red Hills; Bone Spring				
Sec 35, T-24-S, R-33-E					
1150 FSL & 600 FWL	11. County or Parish, State				
	Lea NM				
12. CHECK APPROPRIATE BOX(ES) TO	INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent Acidize	Deepen Production (Start/Resume) Water Shut-Off				
Alter Casing	Fracture Treat Reclamation Well Integrity				
X Subsequent Report Casing Repair	New Construction Recomplete Other				
Change Plans					
Final Abandonment Notice					
Convert to Inj	ection X Plug Back Water Disposal				
If the proposal is to deepen directionally or recomplete horizontally, give Attach the Bond under which the work will be performed or provide the following completion of the involved operations. If the operation result testing has been completed. Final Abandonment Notices shall be filed determined that the final site is ready for final inspection.) 1/25/09 RTH w/ Pinnicale testing equipment. 1/27/09 Pump 3957 bbl mini-frac. POOH and lated the pump state of the pinnicale tools. 1/29/09 RTH w/ Pinnicale tools. 1/30/09 Pump 4891 bbl mini-frac. POOH and lated tools.	y down Pinnicale tools. 59 lbs 100 mesh sand, 25040 lbs 30/60 sand, 10125 lbs k. t 9476'. back.				
14. I hereby certify that the foregoing is true and correct Name (Printed Typed) Stan Wagner Signature Signature	Title Regulatory Analyst Date 2/25/09				
	EDERAL OR STATE OFFICE USF				

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title