



SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other: INJECTION		5. Lease Serial No. NMNM0145685
2. Name of Operator XERIC OIL & GAS COMPANY		6. If Indian, Allottee or Tribe Name
3a. Address P. O. BOX 352 MIDLAND, TX 79702		7. If Unit or CA/Agreement, Name and/or No.
3b. Phone No. (include area code) Ph: 915.683.3171 Ext: 235 Fx: 915.683.6348		8. Well Name and No. HORTON FED 26
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 29 T8S R35E NWNE / 330 N 2310 E		9. API Well No. 30-041-10120-00-S1
		10. Field and Pool, or Exploratory MILNESAND ; San Andres
		11. County or Parish, and State ROOSEVELT COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Deepen
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Fracture Treat
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Recomplete
	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Well Integrity
	<input checked="" type="checkbox"/> Other Final Abandonment Notice
	<input type="checkbox"/> Change Plans
	<input type="checkbox"/> Plug and Abandon
	<input type="checkbox"/> Water Disposal
	<input type="checkbox"/> Convert to Injection
	<input type="checkbox"/> Plug Back

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

SURFACE RECLAMATION HAS BEEN COMPLETED IN ACCORDANCE WITH FEDERAL REQUIREMENTS AND SURFACE OWNER AGREEMENT ATTACHED TO FINAL ABANDONMENT NOTICE FOR HORTON FEDERAL #1. XERIC OIL & GAS CORPORATION REQUESTS APPROVAL OF FINAL ABANDONMENT.
COPY TO OIL OCD DISTRICT I.

RECEIVED

MAR 05 2009

HOBBSOC

14. I hereby certify that the foregoing is true and correct. Electronic Submission #33874 verified by the BLM Well Information System For XERIC OIL & GAS COMPANY, sent to the Roswell Committed to AFMSS for processing by LINDA ASKWIG on 08/02/2004 (04LA0265SE)	
Name (Printed/Typed) ANGIE CRAWFORD	Title SUBMITTING CONTACT
Signature (Electronic Submission)	Date 07/30/2004

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By	Acting Assistant Field Manager, Lands and Minerals	Date 08/27/09
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office ROSWELL FIELD OFFICE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.