

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-025-06027 ✓
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> ✓
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Bertha J. Barber ✓
8. Well Number	13Y ✓
9. OGRID Number	147179 ✓
10. Pool name or Wildcat Monument; Paddock	✓

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator	Chesapeake Operating, Inc. /
3. Address of Operator	P.O. Box 18496 Oklahoma City, OK 73154-0496
4. Well Location	Unit Letter: E : 1980' feet from the North line and 660' feet from the West line Section 8 Township 20S Range 37E NMPM County Lea ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	3552' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL. <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3/7/09 through 3/12/09: MIRU TEST GUY WIRE ANCHORS. PREP LOCATION. MIRU PLUGGING UNIT & SURFACE EQUIP. NDWH, NU BOP. MIRU WIRE LINE UNIT. TIH W/ 5.625 GR. & JB & TAG @ 4975'. RD WIRE LINE UNIT. PU & TIH W/ 150 JTS OF 2 3/8" TBG. NOTIFIED OCD ABOUT HIGH TAG. PBTD SHOULD HAVE BEEN 5025'. OK'D TO START PLUGGING FROM 4975'. CIRCU 7" CSG FROM 4950 TO SURFACE W/ PLUG MUD. LD 60 JTS OF TBG & STAND BACK 90 JTS. TIH W/ WIRE LINE & PERF @ 2950'. PU 7" PKR & 77 JTS OF TBG. SET PKR @ 2556'. EST IN JECTION RATE @ 2 BPM @ 1000 PSI. CMT PUMP BROKE DOWN. MAKE PUMP REPAIRS. SQUEEZE 60 SXS OF CMT INTO PERFS @ 2950'. WOC & TAG @ 2760'. TIH & PERF @ 2167'. TIH W/ PKR & SET @ 1793'. SQUEEZE 50 SXS & WOC TAG PLU @ 2042'. TIH & PERF @ 1150'. TIH W/ TBG & PKR TO 550'. SQUEEZE 80 SXS OF CMT. WOC & TAG @ 900'. TOOH. DUG OUT CELLAR TO FIND 13 3/8" SURFACE VALVE. PERF @ 60' BREAK CIRCU DOWN 7' BETWEEN 9 5/8" & 13 3/8" CSNG. CIRCU 60 SXS OF CMT TO SURFACE IN ALL THREE STRINGS OF CSNG. RIG DOWN PULLING UNIT. WELL P&A ON 3/12/2009. TURN WELL OVER FOR FINAL CLEAN UP.

RECEIVED

Spud Date:

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be released on the Web Page under
Forms, www.emnrd.state.nm.us/sped.

MAR 13 2009

HOBBSDOCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bryan Arrant TITLE Sr. Regulatory Compliance Spec DATE 03/13/2009

Type or print name Bryan Arrant E-mail address: bryan.arrant@clik.com PHONE: (405)935-3782

For State Use Only

APPROVED BY: [Signature] TITLE DISTRICT 1 SUPERVISOR DATE MAR 16 2009

Conditions of Approval (if any):