FORM APPROVED .

August 2007) DEPARTMENT OF THE INTERIOR				OMB NO 1004-0135 Expires July 31, 2010	
SUNDRY	UREAU OF LAND MANA NOTICES AND REPO is form for proposals to	RTS ON WELLS	ECEIVE	5 Lease Serial No. NMLC065194	
abandoned wei	II. Use form 3160-3 (API	D) for such proposals.	AR 1-8 2009	6 If Indian, Allottee	or Tribe Name .
SUBMIT IN TRIPLICATE - Other instructions on reverse side OBBSOCO				7 If Unit or CA/Agreement, Name and/or No NMNM109713	
l Type of Well ☐ Oil Well ☒ Gas Well ☐ Øther				8 Well Name and No BELL LAKE 7909 JV-P 2	
2. Name of Operator Contact PAM INSKEEP BTA OIL PRODUCERS E-Mail: pinskeep@btaoil com				9 API Well No 30-025-34827-0	•
3a Address 3b. Phone No. (include area code) 104 SOUTH PECOS Ph: 432-682-3753 Ext: 139 MIDLAND, TX. 79701 Fx: 432-683-0325				10 Field and Pool, or Exploratory, BELL LAKE; Upper Penn. North Gas	
4. Location of Well (Footage, Sec. T. R. M., or Survey Description)				II County or Parish,	/
Sec 18 T23S R34E SWSE 660FSL 1980FEL				LEA COUNTY,	NM /
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATURE (OF NOTICE, RI	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION		TYP	E OF ACTION	,	·
Notice of Intent	☐ Acidize	☐ Deepen		ion (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing ☐ Fracture Treat ☐ Reclam			_	
-	Classing Repair	New Construction	_		☐ Other
Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	Plug and Abandor ☐ Plug Back	n ☐ Water I	arily Abandon	•
			_		
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for	nally or recomplete horizontally ork will be performed or provided or provided or provided on the operation of the operation	y, give subsurface locations and e the Bond No on file with BLI esults in a multiple completion	measured and true M/BIA. Required s or recompletion in	vertical depths of all per subsequent reports shall a new interval, a Form 3	tinent markers and zones be filed within 30 days 160-4 shall be filed once
BTA proposes to P&A this we	ll as follows:	S		- 477401170	FOD
1) MI & RI completion unit. N 2) PU & RIH w/2-7/8" 6.5# EU 3) Circ hole w/ 9.3# salt gel m 4) Raise end of tbg to 6607'. 5) Circ hole w/ 9.3# salt gel m 6) Spot P&A plugs as follows:	JE Work String to 6600' nud.		CO SEI	E ATTACHED NDITIONS OF	APPROVAL
44 sx @ 6607' 44 sx @ 5110' (Must be tagge 44 sx @ 3500' (Must be tagge 44 sx @ 1105 ' (Must be tagge	ed after spotting) 579 ed after spotting) 479 ed after spotting) 758	0-4960 w 17-4597 w 7-1418 a	oc TAG	6 (Baseof 6 (Top 0) 6 (Shoe	salt) Salt)
G. G	105	5-955 k	OC TA	6 (shoe)

14. Thereby certify that the foregoing is true and correct.

Electronic Submission #67920 verified by the BLM Well Information System

For BTA OIL PRODUCERS, sent to the Hobbs

Committed to AFMSS for processing by KURT SIMMONS on 03/11/2009 (09KMS0557SE) Name (Printed/Typed) BOB STUCKLEY Title IT MANAGER Signature (Electronic Submission) 03/10/2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By (BLM Approver Not Specified)

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Hobbs


Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Additional data for EC transaction #67920 that would not fit on the form

32. Additional remarks, continued

22 sx @ surface Perforate @ 60' Circulate Cont to Surf, infont of 7"
7) Cut off wellhead and install dry hole marker

Schematic attached



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.