Submit 3 Copies To Appropriate District State of New M	exico Form C-103
Submit 3 Copies To Appropriate District Office District 1625 N. French Dr , Hobbs, NM 872 District II OIL: CONSERVATIO	June/19, 2008
1625 N. French Dr , Hobbs, NM 8 24 5 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	WELL API NO. 30 · 041 · 20514
1301 W Grand Ave, Artesia, NM 88240AR 1 90 CONSERVATIO District III 1220 South St. Fr	ancis Dr 5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410BBSOCD Santa Fe, NM 8	STATE X FEE
District IV 1220 S St Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 23844
SUNDRY NOTICES AND REPORTS ON WE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10 PROPOSALS.)	OR PLUG BACK TO A Lambirth State
Type of Well: Oil Well □ Gas Well □ Other SWD	8. Well Number
2. Name of Operator	9. OGRID Number
Energen Resources Corporation	
3. Address of Operator	10. Pool name or Wildcat
3300 N. "A" St., Bldg 4, Ste. 100, Midland, TX 79705 SWO, Fusselman 4. Well Location	
Unit Letter H: 1980 feet from the No	th line and 510 feet from the East line
11. Elevation (Show whether	Range 32E NMPM County Roosevelt DR RKR RT GR etc.)
Tr. Elevation (Show michief Dit, Idit), Art, Oh, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
12. Check Appropriate Box to indicate	Nature of Notice, Report, of Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
DOWNHOLE COMMINGLE	O TOTAL OF THE PARTY SOR
DOWNHOLE COMMININGLE	
OTHER:	OTHER: Acidize and RWTI XX
13. Describe proposed or completed operations. (Clearly state all pe	
of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.	Completions: Attach wellbore diagram of proposed completion
03/04/09 - MIRU Schlumberger. Acidize w/8000 gal of 15% HCL w/additives and 5000# rock salt as follows:	
Stage 1 - pump 200 gal acid. Stage 2 - pump 1000# rock salt in 19.5 bbl gelled 10# brine. Stage 3 - pump 2000 gal acid. Stage 4 - pump 2000# rock salt in 21.4 bbls gelled brine. Stage 5 - pump 2000 gal acid. Stage 6 - pump 2000# rock salt in 18.2 bbl gelled brine. Stage 7 - pump 2000 gal acid. Overflushed w/130 BFW. Ave rate 6.42 B/M, ave PSI 927#, max rate 7.2 B/M, max PSI 2408#. RD Schlumberger, RU wellhead	
RWTI.	
Spud Date: Rig Relea	se Date:
Kig Keica	Sc Date.
I hereby certify that the information above is true and complete to the	best of my knowledge and belief.
SIGNATURE SOLUTION TITI	Regulatory Analyst DATE 03-17-09 nil address: PHONE 432/684-3692
Type or print name Tracie J Cherry E-ma	nil address: PHONE <u>432/684-3692</u>
For State Use Only	DISTRICT 1 SHPERVISOR MAND O A COCO
APPROVED BY TITLE DISTRICT 1 SUPERVISOF DATE MAR 2 0 2009 Conditions of Approval (if apy):	
V	