

RECEIVED

OIL CONSERVATION DIVISION  
MAR 25 2009  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.

30-025-07771

5. Indicate Type of Lease

STATE

FEE ☒

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement Name

Cone "B"

8. Well Number

001

9. OGRID Number

00873

10. Pool name or Wildcat

House : Drinkard

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Apache Corporation

3. Address of Operator

6120 S. Yale Suite 1500, Tulsa OK 74136

4. Well Location

Unit Letter J : 1980 feet from the South line and 1980 feet from the East line  
Section 12 Township 20 S Range 38-E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3,572'

Pit or Below-grade Tank Application ☐ or Closure ☐Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water N/A

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☒CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2/23/09 Move In, Rig Up

2/23/09 Spot 50sx @ 6864'. WOC-Tag @ 6303'

2/24/09 Spot 25sx @ 5682' - 5435'

2/24/09 Spot 125sx @ 4826'. WOC-Tag @ 4219'

2/25/09 Spot 75sx @ 4219'. WOC-Tag @ 4036'

2/25/09 Spot 60sx @ 4036'. WOC-Tag @ 3539'

2/26/09 Cut &amp; Pulled 3469' of 5 1/2" casing

2/27/09 Spot 30sx @ 3519'. WOC-Tag @ 3322'

3/2/09 Perf @ 2920'. Could not get a PIR. Hole is standing full of water. Talk to Mark Whitaker w/ OCD. OK'd spotting plug 50' under perf, no Tag.

3/2/09 Perf @ 1690'. Sqz 40sx. WOC 4 hours. Tag @ 1593'

3/2/09 Perf @ 360'. Sqz 145sx to surface

3/2/09 Rig Down, Move Out, Cut off WH + anchors, install dry hole marker.

Approved for plugging of well bore only.  
Liability under bond is retained pending receipt  
of C-103 (Subsequent Report of Well Plugging)  
which may be found at OCD Web Page under  
Forms, www.emnrd.state.nm.us/oed.I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.SIGNATURE Randall Minear TITLE LA Supervisor (Basic Energy Services) DATE 03/13/09

Type or print name: Randall Minear

E-mail address:

Telephone No. 432-530-0907

For State Use Only

APPROVED BY [Signature] TITLE DISTRICT 1 SUPERVISOR DATE MAR 24 2009

Conditions of Approval (if any):