Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM A	PPRO	VED
OMB No	1004-	0137
Expures 1	ulv 31	2010

5. Lease Serial No.

LC-031621-A

6 If Indian, Allottee or Tribe Name

apandoned well.	Use Form 3160-3 (Al	PD) for such proposals.	
SUBMIT IN TRIPLICATE – Other instructions on page 2.		7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well Oil Well Gas W	Vell Other	/	8. Well Name and No. H. M. Britt No. 10
2. Name of Operator EnerVest Opera	ating, L.L.C.		9 API Well No. 30-025-05997 J
3a Address 1001 Fannın, Suite 8i Houston, TX 77002		3b. Phone No (include area code) 713-495-6537	10. Field and Pool or Exploratory Area Upper Eumont (Yates-7 Rivers)
4. Location of Well (Footage, Sec., T.,	R.,M, or Survey Description)	Sec 7 - Twp 20S - Rge 37E 330' FNL and 1650' FEL (Unit B)	11 Country or Parish, State Lea County, NM
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO INDICATE NATURE OF NOT	ICE, REPORT OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION		
✓ Notice of Intent	Acidize Alter Casing	_ = ' = =	oduction (Start/Resume)
Subsequent Report	Casing Repair		complete Other mporarily Abandon
Final Abandonment Notice	Change Plans Convert to Injection		ater Disposal
the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BLA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) EnerVest Operating, L.L.C. respectfully requests a 1 year TA extension so that we may properly evaluate the well.			
APROV APR 4 JAMES A. A SUPERVISOR	2009 MOS	RECEIVED APR 0 / 2009 HOBBSOUD	SEE ATTACHED FOR CONDITIONS OF APPROVAL Test well within 30 days.
14 I hereby certify that the foregoing is t	rue and correct Name (Printed	VTyped)	

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Signature

DISTRICT 1 SUPERVISOR

APR 08 2009

Conditions of approval, if any, are attached Approval of this notice does not warrant or cerufy that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

Date 03/25/2009

Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for a 12 month period provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- Describes the temporary abandonment procedure.
- Attaches a clear copy or the original of the pressure test chart.

The TA status could be extended for an additional 12 month period without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative. The operator must submit a sundry notice requesting an extension of TA status 30 days prior to expiration of the previous approval and appropriate justification for extending the TA status is included.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

WWI 012908